

# Cisco WAP371 Wireless Access Points, Firmware Version 1.2.0.2

Version 1.2.0.2

June, 2015

These release notes describe the open issues for the Cisco WAP371 Wireless Access Points.

## Requirements

- Your computer must meet the recommended hardware and software requirements.
- A computer with Browser support for:
  - Internet Explorer v7.0 or later
  - Chrome v5.0 or later
  - Firefox v3.0 or later
  - Safari v3.0 or later

## New in This Release

- IGMP Snooping
- 802.11w - PMF
- TurboQAM supported for 11AC PHY's

## Resolved Issues

- CSCuq9394 1: When traffic on tagged VLAN the throughput (especially download) is very slow.

## Release Notes

---

- CSCuq92093: Email alert is blank with Microsoft Exchange Server 2007 or 2010
- CSCus78507: GUI issue for “Session Key Refresh Rate”
- CSCuu34454: Improvement for multi-client throughput
- CSCul96092: On latest builds user is able to configure SSID with all special characters. But on the networks help page, help content is not updated accordingly.

## Open Caveats

These are the open caveats for firmware version 1.2.0.2

**Table 1 Open Caveats in Firmware Version 1.2.0.2**

Ref Number	Description
CSCui10930	<b>Symptom:</b> Configure excluded view cannot access all MIB tree. <b>Workaround:</b> None.
CSCuh42442	<b>Symptom:</b> When users assign a schedule profile to VAP, the schedule rule ONLY impacts the defined scope. Weekend refers to Sunday and Saturday and daily means every day. <b>Workaround:</b> None.

## Related Information

Support	
Cisco Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Phone Support Contacts	<a href="http://www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html">www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html</a>
EU lot 26	For EU lot 26 related test result, please check this web page: <a href="http://www.cisco.com/go/eu-lot26-results">www.cisco.com/go/eu-lot26-results</a>
Cisco Firmware Downloads	<a href="http://www.cisco.com/go/smallbizfirmware">www.cisco.com/go/smallbizfirmware</a> Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	<a href="http://www.cisco.com/go/smallbiz_opensource_request">www.cisco.com/go/smallbiz_opensource_request</a>
Cisco Partner Central (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Product Documentation	
Cisco WAP551 and WAP561 Administration Guide	<a href="http://www.cisco.com/go/500_wap_resources">www.cisco.com/go/500_wap_resources</a>
Cisco Power Adaptors	<a href="http://www.cisco.com/go/wap_accessories">www.cisco.com/go/wap_accessories</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2015 Cisco Systems, Inc. All rights reserved.