

# Release Notes for the Cisco WAP571-571E Wireless-AC Dual Radio Access Points Firmware Version, 1.1.0.5

## Contents

This document includes the following topics:

- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.5, page 2](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.4, page 2](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.3, page 3](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.2.6, page 3](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.12, page 4](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.11, page 5](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.10, page 6](#)
- [Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.9, page 7](#)
- [Related Information, page 9](#)

# Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.5

## Feb 2020

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version 1.1.0.5

## Resolved Issues

The following issues have been fixed in firmware version 1.1.0.5:

Ref Number	Description
CSCvs93095	Evaluation of wap571 for Kr00k attack - CVE-2019-15126.

# Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.4

## Jul 2019

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version 1.1.0.4

## Resolved Issues

The following issues have been fixed in firmware version 1.1.0.4:

Ref Number	Description
CSCvq31963	Evaluation of wap571 for TCP SACK vulnerabilities.

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.1.0.3

**Apr 2019**

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version 1.1.0.3.

### What's New

New GUI Style

Support for External Captive Portal (Purple WIFI)

Support Cisco PnP

### Unknown Issues

Currently, only English Online help (OLH) supports the External Captive Portal and PnP feature

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.2.6

**Sept 2018**

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version, 1.0.2.6.

### What's New

Mobile setup wizard

Website filtering using Cisco Umbrella

Packet capture with Cloudshark

Captive portal login with Windows Active Directory Domain Services (ADDS)

Captive portal login with Facebook and Google

### Known Issues

The following table lists the known issues in firmware version 1.0.2.6:

Ref Number	Description
CSCvj69001	The Captive portal page doesn't display when a wireless client tries to open HSTS website using a Browser that supports HSTS  <b>Workaround</b> Try using a non HSTS website to trigger the Captive Portal feature

### Resolved Issues

The following issues have been fixed in firmware version 1.0.2.6

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly
CSCvi23179	PoE power fails to negotiate correctly with Catalyst switch
CSCvn36130	Unable to select auto Channel with the latest firmware
CSCvn80497	wl1: wlc_reset: !!!BIG-hammer!!!. PSM microcode watchdog fired

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.12

### Mar 2018

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version, 1.0.1.12.

### Enhancements

Support new NAND flash

## Known Issues

The following table lists the known issues in firmware version 1.0.1.12:

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly <b>Workaround</b> None

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.11

### Nov 2017

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version, 1.0.1.11

### Enhancements

Support of new EU regulation

### Resolved Issues

The following issues have been fixed in firmware version 1.0.1.11

Ref Number	Description
CSCvf96820	Key Reinstallation attacks against WPA protocol

### Known Issues

The following table lists the known issues in firmware version 1.0.1.11:

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly <b>Workaround</b> None

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.10

### June 2017

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version, 1.0.1.10

### Enhancements

Support of new EU regulation

### Resolved Issues

The following issues have been fixed in firmware version 1.0.1.10

Ref Number	Description
CSCve11798	Spectrum Analyzer doesn't open when accessed using hostname

### Known Issues

The following table lists the known issues in firmware version 1.0.1.10:

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly <b>Workaround</b> None

## Cisco WAP571-571E Wireless Access Points, Firmware Version, 1.0.1.9

### March 2017

These release notes describe the known issues in the Cisco WAP571-571E Wireless-AC Dual Radio Access Points firmware version, 1.0.1.9

### Enhancements

Support of new EU regulation

Support of Cisco FindIt Network Management

Support Russia SKU

Support English/French/Chinese/German Online Help

### Resolved Issues

The following issues have been fixed in firmware version 1.0.1.9

Ref Number	Description
CSCva28888	WAP571: Some egress packets from tagged VLAN are untagged
CSCve11798	Spectrum Analyzer doesn't open when accessed using hostname
CSCux49554	When using MAC OS connect to CiscoSB-Setup, a page pops up but fails to login

## Release Notes

---

### Known Issues

The following table lists the known issues in firmware version 1.0.1.9:

Ref Number	Description
CSCvd52825	Remote packet capture function not working correctly <b>Workaround</b> None



## Related Information

Support	
Cisco Support Community	<a href="http://www.cisco.com/go/smallbizsupport">www.cisco.com/go/smallbizsupport</a>
Cisco Support and Resources	<a href="http://www.cisco.com/go/smallbizhelp">www.cisco.com/go/smallbizhelp</a>
Phone Support Contacts	<a href="http://www.cisco.com/go/sbsc">www.cisco.com/go/sbsc</a>
Cisco Firmware Downloads	<a href="http://www.cisco.com/go/smallbizfirmware">www.cisco.com/go/smallbizfirmware</a> Select a link to download firmware for Cisco Products. No login is required.
Cisco Open Source Requests	<a href="http://www.cisco.com/go/smallbiz_opensource_request">www.cisco.com/go/smallbiz_opensource_request</a>
Cisco Partner Central (Partner Login Required)	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>
Product Documentation	
Cisco WAP571 and WAP571E	<a href="http://www.cisco.com/go/500_wap_resources">www.cisco.com/go/500_wap_resources</a>
Regulatory Compliance and Safety Information	<a href="http://www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap571_571E/RCSI/EU-RCSI_WAP571.pdf">www.cisco.com/c/dam/en/us/td/docs/wireless/access_point/csbap/wap571_571E/RCSI/EU-RCSI_WAP571.pdf</a>
Warranty Information	<a href="http://www.cisco.com/go/warranty">www.cisco.com/go/warranty</a>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.