



日本市場向け
Cisco Prime Infrastructure 3.3
システム リリース テスト結果サマリ

シスコシステムズ合同会社

2018 年 01 月

コンポーネント一覧 (1)

Category	Component	Version
Controller	Wireless LAN controller 3504	8.7.1.112
	Wireless LAN Controller 5520	8.7.1.112
	Wireless LAN controller 8540	8.7.1.112
	Virtual Controller	8.7.1.112
	APIC-EM Controller Appliance	1.6
	ME 1852/1832/1815I	8.7.1.112
	ME 1562I	8.7.1.112
	ME 2800/3800	8.7.1.112
Applications	Prime Infrastructure(Virtual Appliance, UCS based)	3.3.0.0.342
	ISE(Virtual Appliance)	2.4
	Secure ACS(Virtual Appliance)	5.8.1
	MSE	8.0.130.0
	CMX, CMX Cloud	10.4
	Cisco Jabber for Windows, iPhone	11.8.0
	Cisco Air Provisioning App	1.4
	Cisco Wireless App	1.0.228

コンポーネント一覧 (2)

Category	Component	Version
Access Points	Cisco AP 3700	15.3
	Cisco AP 2700	15.3
	Cisco AP 1600	15.3
	Cisco AP 1700	15.3
	Cisco AP 1540	15.3
	Cisco AP 702I	15.3
	Cisco AP 1570	15.3
	Cisco AP 1850	15.3
	Cisco AP 1830	15.3
	Cisco AP 1815W	15.3
	Cisco AP 1815I	15.3
	Cisco AP 1810	15.3
	Cisco AP 2800	15.3
	Cisco AP 3800	15.3
	Cisco AP 1560	15.3
	Cisco AP 1530	15.3
Antenna	Hyper Location	NA

コンポーネント一覧 (3)

Category	Component	Version
Switch	Cisco Cat 6509-E	15.1(1)SY1
	Cisco 3750V2 switch	15.0(2)SE2
	Cisco Cat 9300	16.7.1
Chipset	5300, 6300 AGN	15.13.0.2
	7265 AC	19.10.0.9
	Airport Extreme	7.7
Clients	Operating System(JOS)	Windows 7 Enterprise Windows 8 & 8.1 Enterprise Windows XP Professional Windows 10
	Apple Mac Book Pro (JP Locale)	Mac OS 10.13.2
	iPad Pro	iOS 11.2.2(15C202)
	iPhone 6, 6S & 7 (JP Locale)	iOS 11.2.2(15C202)
	Samsung Galaxy S4 & S7, Nexus 6P, Sony Xperia XZ	Android 8.0
	Wireless IP Phone 8821	11-0-3-99

コンポーネント一覧 (4)

Category	Component	Version
Active Directory	AD	Windows 2008R2Enterprise
Browsers	IE	11.0
	Mozilla Firefox	57.0
	Safari	11.0
	Chrome	63.0
Clients	Cisco AnyConnect VPN Client	4.5.03040
	End points	Windows 7 Enterprise Apple Mac OS 10.11.6 Windows 8, 8.1 & 10 iPhone 6,6S & 7 Samsung Galaxy S4, S7 & Nexus 6P

新規機能

- Rolling AP Upgrade
- Monitor Mode support in APs(1810/1815)
- Wireless Rogue Requirements
- AP Health Extension
- WLC Health Scoring
- EoGRE Profile
- WLC3504 Support
- Support Flex+Bridge mode configuration for Aps
- Support Hyperlocation config enhancement in Lightweight AP template
- Scheduled AP upgrade
- Outdoor AP GPS support

既存機能

- Custom Reports
- Config Group Phase 2
- Network Health – Wireless Client and Rogue
- Next Generation Maps
- DHCP server to ME
- TrustSec SGT/SG ACL for Wireless (WLC)
- MAC filtering capability for lobby ambassadors
- Domain based URL ACL
- Autonomous AP to LWAPP Migration
- High Availability
- Flex AVC
- APIC-EM Integration
- SWIM Enhancements
- HA Enhancements
- Guest Anchor Priority

既存機能

- End to end CMX Integration testing
- Rolling AP Upgrade
- Monitor Mode support in Aps(1810/1815)
- AP Health Extension
- WLC Health Scoring
- EoGRE
- Support Flex + Bridge mode configuration for Access points
- WLC 3504 Support
- Wireless User View
- Enhance Wireless Data and Troubleshooting
- FlexConnect Mode Feature Parity with IOS Aps
- Wireless Dashboard

テスト結果

対象コンポーネント	テスト項目数	合格数	不合格数	不具合数
新規機能	194	157	2	2
既存機能	647	619	32	32
合計	841	766	34	34

Resolved Caveats

DDTS ID	タイトル	Severity	製品	機能/ コンポーネント	新規機能/ 既存機能	ステータス
CSCvf93055	PI: Options like Save, Reset & Factory-Reset buttons disabled in SPT config	3	ncs	i18n	既存機能	改修済み
CSCvf94501	Duplicate IP address gets accepted in Tunnel Gateway template in PI	3	ncs	wireless-ui	既存機能	改修済み
CSCvf94683	PI: User is able to config WLAN name with more than 32 characters	3	ncs	config-wireless	既存機能	改修済み
CSCvg10066	PI:No validation for VLAN ID in policy Name page	3	ncs	config-wireless	既存機能	改修済み
CSCvg25060	Image is not being uploaded to Sites in Maps	3	ncs	maps	既存機能	改修済み
CSCvg25298	User is not able to config RF Profile which name is in Japanese character via PI	3	ncs	config-wireless	既存機能	改修済み
CSCvg29239	AVC rule created in avc profile cannot be deleted .	3	wlc	wlc-qos	既存機能	改修済み

Resolved Caveats

DDTS ID	タイトル	Severity	製品	機能/ コンポーネント	新規機能/ 既存機能	ステータス
CSCvg30737	Wireless Controllers data is not exporting all details while user exports the data in PI	3	ncs	inventory	既存機能	改修済み
CSCvg30858	User defined OUI cannot be created in PI	3	ncs	i18n	既存機能	改修済み

Open Caveats

DDTS ID	タイトル	Severity	製品	機能/ コンポーネント	新規機能/ 既存機能	ステータス
CSCvg13050	Mismatch the max client values in WLC and PI	3	ncs	wireless-ui	新規機能	未改修
CSCvg88521	PI: Popup message displayed always while configuring the Multicast parameters in PI for WLC	3	ncs	config-wireless	新規機能	未改修
CSCvh09969	Import AP Config showing Irrelevant data under AP Radio Page in PI.	3	ncs	i18n	新規機能	未改修
CSCvh12451	In PI Unable to delete AVC rule created in AVC profile .	3	ncs	config-wireless	既存機能	未改修
CSCvh16178	WLAN template is not deploying in PI while login to japanese language	3	ncs	i18n	新規機能	未改修
CSCvh17371	Flex AVC rule not getting reflected in PI under Flex AVC profile	3	ncs	config-wireless	既存機能	未改修
CSCvh24523	Unable to configure the wlan profile in PI localized GUI	3	ncs	i18n	既存機能	未改修

Open Caveats

DDTS ID	タイトル	Severity	製品	機能/ コンポーネント	新規機能/ 既存機能	ステータス
CSCvh31820	Ip address can be edited when enabling DHCP in Service port	3	ncs	config-wireless	新規機能	未改修
CSCvh32295	Shown error message while deploy the EoGRE profile template in PI GUI	3	ncs	i18n	新規機能	未改修
CSCvh58033	Options like deploy,undeploy & history are missing when navigating from Mac Filtering to WLAN Config	3	ncs	config	新規機能	未改修



CISCO

TOMORROW starts here.