



END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO TRANSPORT MANAGER RELEASES 2.2 AND 3.1

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® Transport Manager Release 2.2 and Release 3.1. The last day to order Cisco Transport Manager releases 2.2 and 3.1 is February 23, 2005. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until February 23, 2008. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Transport Manager Release 2.2 and Release 3.1. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the latest release of Cisco Transport Manager, which provides enhanced functions and supports the latest releases of the managed network elements. Information about this product can be found at:

<http://www.cisco.com/en/US/products/sw/opticsw/ps2204/>

Table 3 provides relevant information for migrating from Cisco Transport Manager Release 2.2 and Release 3.1 to Cisco Transport Manager Release 4.7, which is the current general availability release at the issue date of this notice.

Before upgrading Cisco Transport Manager, always check that the new release supports the release of network elements to be managed. Support information is available in the release notes, available at:

http://www.cisco.com/en/US/products/sw/opticsw/ps2204/prod_release_notes_list.html

Table 1. End-of-Life Milestones and Dates for the Cisco Transport Manager Release 2.2 and Release 3.1

Milestone	Definition	Date
End-of-life announcement date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	August 23, 2004
End-of-sale date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 23, 2005
Last shipment date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 23, 2005
End of software maintenance releases date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 23, 2006
End of new service attachment date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 23, 2006
End of service contract renewal date	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	November 23, 2007
Last date of support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 23, 2008

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
CTM-2.2-BLS=	Cisco Transport Manager Release 2.2 Baseline System Package
CTM-2.2-UPG=	Cisco Transport Manager Release 2.2 Upgrade Package
CTM-2.2-010=	Additional CTM Client R2.2—10 Blk
CTM-2.2-025=	Additional CTM Client R2.2—25 Blk
CTM-2.2-050=	Additional CTM Client R2.2—50 Blk
CTM-3.1-SMK=	CTM R3.1 Software Media Kit
CTM-3.1-UPG=	CTM R3.1 Upgrade, R3.0(.x) to R3.1
CTM-3.1-CORBA=	CTM GateWay/CORBA Northbound Interface R3.1
CTM-3.1-CORBA-UPG=	CTM GateWay/CORBA NBI Upgrade, R3.0(.x) to R3.1
CTM-3.1-HA=	CTM R3.1 High Availability Agent R2.0
CTM-3.1-HA-UPG=	CTM R3.1 High Availability Upgrade, R3.0(.x) to R3.1
Associated NE RTUs	
CTM-15200-001	Cisco ONS 15200 RTU License—1 RTU
CTM-15200-025=	Additional Cisco ONS 15200 RTU LICENSE—25 BLK
CTM-15200-050=	Additional Cisco ONS 15200 RTU LICENSE—50 BLK
CTM-15200-100=	Additional Cisco ONS 15200 RTU LICENSE—100 BLK
CTM-15216-001=	CTM Cisco ONS 15216 RTU LICENSE—1 RTU
CTM-15216-025=	CTM Cisco ONS 15216 RTU LICENSE—25 RTU
CTM-15216-050=	CTM Cisco ONS 15216 RTU LICENSE—50 RTU
CTM-15216-100=	CTM Cisco ONS 15216 RTU LICENSE—100 RTU
CTM-15327-001	Cisco ONS 15327 RTU License—1 RTU
CTM-15327-025	ADDITIONAL CISCO 15327 RTU LICENSE—25 BLK
CTM-15327-050	ADDITIONAL CISCO 15327 RTU LICENSE—50 BLK
CTM-15327-100	ADDITIONAL CISCO 15327 RTU LICENSE—100 BLK
CTM-15454-001	Cisco ONS 15454 RTU License—1 RTU
CTM-15454-025	ADDITIONAL CISCO 15454 RTU LICENSE—25 BLK
CTM-15454-050	ADDITIONAL CISCO 15454 RTU LICENSE—50 BLK
CTM-15454-100	ADDITIONAL CISCO 15454 RTU LICENSE—100 BLK
CTM-15454-500	ADDITIONAL CISCO 15454 RTU LICENSE—500 BLK
CTM-1580X-001	CTM NE RTU for 1580X
CTM-1580X-005	ADDITIONAL CISCO 1580X RTU LICENSE—5 BLK
CTM-1580X-010	ADDITIONAL CISCO 1580X RTU LICENSE—10 BLK
CTM-1580X-025	ADDITIONAL CISCO 1580X RTU License—25 Block
CTM-1580X-050	ADDITIONAL CISCO 1580X RTU License—50 Block
CTM-1580X-100	ADDITIONAL CISCO 1580X RTU License—100 Block
CTML-15200-010	Cisco Transport Manager RTU License for 15200—10 Block
CTML-15200-025	Cisco Transport Manager RTU License for 15200—25 Block

End-of-Sale Product Part Number	Product Description
CTML-15200-050	Cisco Transport Manager RTU License for 15200—50 Block
CTML-15216-025	Cisco Transport Manager RTU License for 15216—25 Block
CTML-15302-050	Cisco Transport Manager RTU License for 15302—50 Block
CTML-15305-050	Cisco Transport Manager RTU License for 15305—50 Block
CTML-15327-050	Cisco Transport Manager RTU License for 15327—50 Block
CTML-15530-005	Cisco Transport Manager RTU License for 15530—5 Block
CTML-15540-005	Cisco Transport Manager RTU License for 15540—5 Block
CTML-1580X-005	Cisco Transport Manager RTU License for 1580x—5 Block
CTML-1580X-010	Cisco Transport Manager RTU License for 1580x—10 Block
CTML-1580X-025	Cisco Transport Manager RTU License for 1580x—25 Block

PRODUCT MIGRATION OPTIONS

The recommended replacement for Cisco Transport Manager Release 2.2 and Release 3.1 is Cisco Transport Manager Release 4.7 (Table 3) or the current general availability release of Cisco Transport Manager. Before upgrading Cisco Transport Manager check that the new release supports the release of network elements to be managed. Support information is available in the release notes, available at:

http://www.cisco.com/en/US/products/sw/opticsw/ps2204/prod_release_notes_list.html

Table 3. Product Comparisons

Cisco Transport Manager Releases 2.2, 3.1	Cisco Transport Manager Release 4.7
CTM-2.2-BLS=	CTM-4.6-SMK=
CTM-2.2-UPG=	CTM-3.2-4.6-UPG=
CTM-2.2-010=	CTM-CLIENT-010
CTM-2.2-025=	No direct replacement
CTM-2.2-050=	CTM-CLIENT-050
CTM-3.1-SMK=	CTM-4.6-SMK=
CTM-3.1-UPG=	CTM-3.2-4.6-UPG=
CTM-3.1-CORBA=	CTM-4.6-CORBA=
CTM-3.1-CORBA-UPG=	CTM-4.6-CORBA-UPG=
CTM-3.1-HA=	CTM-4.6-HA=
CTM-3.1-HA-UPG=	CTM-4.6-HA-UPG=

Network element Right to Use (RTU) licenses do not need to be upgraded; they are release independent. RTU licenses that were purchased for Cisco Transport Manager Release 2.2 or 3.1 are still valid for Cisco Transport Manager Release 4.7. New RTU licenses can be purchased for additional network elements that are added to the network.

Customers who have a current Software Application Support plus Upgrades (SASU) contract can use the Product Upgrade Tool (PUT) to get the software upgrade at:

<http://tools.cisco.com/gct/Upgrade/jsp/index.jsp>



FOR MORE INFORMATION

For more information about the Cisco Transport Manager, visit

<http://www.cisco.com/en/US/products/sw/opticsw/ps2204/>

or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International
BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland
Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland
Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R)

203073_ETMG_SM_08.04