



## End-of-Sale and End-of-Life Announcement for the Cisco TelePresence MCU MSE 8420 Blade

EOL9136

Cisco announces the end-of-sale and end-of-life dates for the Cisco TelePresence MCU MSE 8420 Blade. The last day to order the affected product(s) is September 27, 2013. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

**Table 1.** End-of-Life Milestones and Dates for the Cisco TelePresence MCU MSE 8420 Blade

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	March 29, 2013
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 27, 2013
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 26, 2013
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 27, 2014
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	September 27, 2014
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 27, 2014
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	December 23, 2017
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2018

HW = Hardware   OS SW = Operating System Software   App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CTI-8420-MED-K9	MCU MSE 8420 - (Media) MCU blade up to 40 MCU (Media) Ports	CTI-8510-MED2-K9	MCU MSE 8510 - (Media2) MCU blade up to 80 MCU (Media) Ports	-
CTI-8420-MED-K9=	MCU MSE 8420 - (Media) MCU blade up to 40 MCU (Media) Ports	CTI-8510-MED2-K9	MCU MSE 8510 - (Media2) MCU blade up to 80 MCU (Media) Ports	-
CTI-ATP-8420-K9	MCU MSE 8420 - (Media) MCU blade up to 40 MCU (Media) Ports	CTI-8510-MED2-K9	MCU MSE 8510 - (Media2) MCU blade up to 80 MCU (Media) Ports	-
CTI-ATP-8420-K9=	MCU MSE 8420 - (Media) MCU blade up to 40 MCU (Media) Ports	CTI-8510-MED2-K9	MCU MSE 8510 - (Media2) MCU blade up to 80 MCU (Media) Ports	-
L-8420-CCD	Order L-8000-BLADE-PAKforMSE 8420 Blade Conf. Director Option	There is currently no replacement product available for this product.	-	-
LIC-8420-CCD	Conference Director Option For MSE 8420 Blade	There is currently no replacement product available for this product.	-	-
LIC-8420-HRO	HRO-8420 High Resolution Option For The MSE 8420	There is currently no replacement product available for this product.	-	-
LIC-8420-MED-K9	License Key For MSE 8420 Software Image, Used During DF	There is currently no replacement product available for this product.	-	-
LIC-8420-VFO	MSE-8420 Video Firewall Option	There is currently no replacement product available for this product.	-	-
LIC-8420-WCO	WCO-8420 Web Conferencing Option For The MSE8420	There is currently no replacement product available for this product.	-	-
SW-8420-MED-K9	Software Image For MSE 8420 Media Blade, Latest Version	There is currently no replacement product available for this product.	-	-

## Product Migration Options

Customers are encouraged to migrate to the Cisco TelePresence MCU MSE 8510 Blade. Information about this product can be found at:

[http://www.cisco.com/en/US/prod/collateral/ps7060/ps11305/ps11317/ps11340/data\\_sheet\\_c78-627558.html](http://www.cisco.com/en/US/prod/collateral/ps7060/ps11305/ps11317/ps11340/data_sheet_c78-627558.html).

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

[http://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco TelePresence MCU MSE 8420 Blade through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

---

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

### For More Information

For more information about the Cisco TelePresence MCU MSE 8510 Blade, visit

[http://www.cisco.com/en/US/prod/collateral/ps7060/ps11305/ps11317/ps11340/data\\_sheet\\_c78-627558.html](http://www.cisco.com/en/US/prod/collateral/ps7060/ps11305/ps11317/ps11340/data_sheet_c78-627558.html), or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

### Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)