



END-OF-LIFE NOTICE, NO. 2348

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR CISCO IOS 12.2 FOR THE uBR7200 PLATFORM

Cisco Systems® announces the End-of-Life of Cisco® IOS® 12.2 for the uBR7200 platform. The last day to order Cisco IOS 12.2 for the uBR7200 platform was May 7, 2002. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until May 7, 2007. Table 1 describes the End-of-Life milestones, definitions, and dates for Cisco IOS 12.2 for the uBR7200 platform.

Customers are encouraged to migrate to Cisco IOS 12.1EC for the uBR7200, which contains the latest bug fixes and feature support for the uBR7200 platform.

Table 3 provides relevant information for migrating from Cisco IOS 12.2 for the uBR7200 platform to Cisco IOS 12.1EC.

Table 1. End-of-Life Milestones and Dates for Cisco IOS 12.2 for the uBR7200 Platform

Milestone	Definition	Date
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	May 7, 2002
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	May 7, 2003
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	May 7, 2007

Table 2. Cisco IOS Images and Product Codes Affected by This Announcement

Platform	Software Feature Set	Product Code	Image
uBR7200	DOCSIS® 2-Way BPI IP+	SU7PK8-12210	uBR7200-ik8s-mz
uBR7200	DOCSIS 2-Way BPI Telco Return IP+	SU7PK8T2-12210	uBR7200-ik8st-mz
uBR7200	DOCSIS 2-Way IP+	SU7M3P-12210	uBR7200-is-mz
uBR7200	DOCSIS 2-Way Telco Return IP+	SU7M3PT2-12210	uBR7200-ist-mz
uBR7200	DOCSIS 2-Way	SU7M3-12210	uBR7200-p-mz

PRODUCT MIGRATION OPTIONS

The recommended replacement for Cisco IOS 12.2 for the uBR7200 platform is Cisco IOS 12.1EC (Table 3). Cisco IOS 12.1EC contains the latest bug fixes and new features for the uBR7200 platform.

Table 3. Product Comparisons

IOS 12.2 Image Description	Cisco IOS 12.2 forubr7200 Product Code	Cisco IOS 12.1EC Migration Image	Cisco IOS 12.1EC Product Code
DOCSIS 2-Way BPI IP+	SU7PK8-12210	DOCSIS 2-Way BPI IP+	SU7PK4-12119EC
DOCSIS 2-Way BPI Telco Return IP+	SU7PK8T2-12210	DOCSIS 2-Way BPI Telco Return IP+	SU7PK4T2-12119EC
DOCSIS 2-Way IP+	SU7M3P-12210	DOCSIS 2-Way BPI IP+	SU7PK4-12119EC
DOCSIS 2-Way Telco Return IP+	SU7M3PT2-12210	DOCSIS 2-Way BPI Telco Return IP+	SU7PK4T2-12119EC
DOCSIS 2-Way	SU7M3-12210	DOCSIS 2-Way BPI	SU71M3K4-12119EC

ADDITIONAL INFORMATION

For more information about Cisco products, please contact your Cisco account manager or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive EOL/EOS information, please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

DOCSIS is a registered trademark of Cable Television Laboratories, Inc. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05