



PRODUCT BULLETIN 2505

CISCO IOS SOFTWARE RELEASE 12.0(5)WC10

This product bulletin delineates content and delivery information about Cisco IOS® Software Release 12.0(5)WC10. This release is only for the Cisco® Catalyst® 2900 Series XL, Cisco Catalyst 2900 Series LRE XL, and Cisco Catalyst 3500 Series XL switches.


Note: For more information about the Cisco IOS Software release process, please see Product Bulletin 537.

MIGRATION GUIDE

Figure 1 shows the Cisco IOS Software Release 12.0(5)WC10 functions relative to the 12.0 and 12.0T releases and identifies the recommended migration path. Also, the recommended migration path for the Cisco Catalyst 2900 Series XL and Cisco Catalyst 3500 Series XL switches is shown.

Figure 1

Cisco IOS Software Release 12.0(5)WC10 Release Train and Migration Plan for the Cisco Catalyst 2900 Series XL, Catalyst 2900 LRE XL, and Catalyst 3500 Series XL Switches



Cisco Systems, Inc.

All contents are Copyright © 1992–2004 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

NEW FEATURES IN CISCO IOS SOFTWARE RELEASE 12.0(5)WC10

Cisco IOS Software Release 12.0(5)WC10 is a maintenance release. There are no new feature enhancements.

DETAILED INFORMATION

For more information about Cisco IOS Software Release 12.0(5)WC10, see the Release Notes at:

<http://www.cisco.com/univercd/cc/td/doc/product/lan/c2900xl/index.htm>.

SUPPORT

Cisco IOS Software Release 12.0(5)WC10 follows the standard Cisco support policy, which is available at:

<http://cisco.com/en/US/support/index.html>.

Table 1. Cisco IOS Software Releases for Cisco Catalyst 2900 Series XL, Catalyst 2900 Series LRE XL, and Catalyst 3500 Series XL Switches

Platform	Cisco IOS Software Feature Set	Product Code	Image	Flash	DRAM
Cisco Catalyst 2900 Series XL	12.0(5)WC10	N/A	c2900xl-c3h2s-mz.120-5.WC10.bin	4 MB	8 MB
Cisco Catalyst 2900 Series LRE XL	12.0(5)WC10	N/A	c2900xl-c3h2l9s-mz.120-5.WC10.bin	8 MB	16 MB
Cisco Catalyst 3500 Series XL	12.0(5)WC10	N/A	c3500xl-c3h2s-mz.120-5.WC10.bin	4 MB	8 MB

Customers can download Cisco IOS Software Release 12.0(5)WC10 from the Cisco Software Center at:

<http://www.cisco.com/public/sw-center/sw-ios.shtml>.

In addition, the following pages on Cisco.com host platform-specific images:

Cisco Catalyst 2900 Series LRE XL Switch with Cisco IOS Software:

<http://www.cisco.com/cgi-bin/tablebuild.pl/cat2900LRE>.

Cisco Catalyst 2900 Series XL Switch with Cisco IOS Software:

<http://www.cisco.com/cgi-bin/tablebuild.pl/cat2900XL>.

Cisco Catalyst 3500 Series XL Switch with Cisco IOS Software:

<http://www.cisco.com/cgi-bin/tablebuild.pl/cat3500XL>.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International
BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, the Cisco Systems logo, Catalyst, and Cisco IOS are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0403R) 204064_ETMG_WH_05.04

