

## End-of-Sale and End-of-Life Announcement for the Cisco IOS Software Release 12.3(7)XI on the Cisco 10008 Router

EOL6338

Cisco® announces the end-of-sale and end-of life dates for the Cisco IOS Software Release 12.3(7)XI on the Cisco 10008 Router. The last day to order the affected product(s) is November 20, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Customers are encouraged to migrate to the Cisco IOS Software Release 12.2(31)SB, which includes new features for the Cisco 10008 Router, including high availability and many other enhancements. Information about the replacement product can be found at: <http://www.cisco.com/en/US/products/hw/routers/ps133/index.html>. Table 2 provides relevant information for migrating to the replacement product.

**Table 1.** End-of-Life Milestones and Dates for the Cisco IOS Software Release 12.3(7)XI on the Cisco 10008 Router

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	June 1, 2008
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 30, 2008
<b>Last Ship Date: OS SW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 30, 2008
<b>End of SW Maintenance Releases Date: OS SW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 30, 2009
<b>Last Date of Support:</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 29, 2013

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
<b>S10KK5Z-12307XI</b>	Cisco 10000 Series IOS BROADBAND ROUTER 8K SECURE SHELL 3DES	S103K91Z-12231SB	Cisco 10K PRE3 IOS UPTO 8K SUBSCRIBERS W/3DES
<b>S10KK5Z-12307XI=</b>	Cisco 10000 Series IOS BROADBAND ROUTER 8K SECURE SHELL 3DES	S103K91Z-12231SB=	Cisco 10K PRE3 IOS UPTO 8K SUBSCRIBERS W/3DES

<b>S10KK8ZU-12307XI</b>	Cisco 10000 Series IOS LAWFUL INTERCEPT/SECURED SHELL DES	S103K9ZU-12231SB	Cisco 10K PRE3 IOS UP TO 8K SUBS W/LAWFUL INTERCEPT 3DES
<b>S10KK8ZU-12307XI=</b>	Cisco 10000 Series IOS LAWFUL INTERCEPT/SECURED SHELL DES	S103K9ZU-12231SB=	Cisco 10K PRE3 IOS UP TO 8K SUBS W/LAWFUL INTERCEPT 3DES
<b>S10KK9ZU-12307XI</b>	Cisco 10000 Series IOS LAWFUL INTERCEPT/SECURED SHELL 3DES	S103K9ZU-12231SB	Cisco 10K PRE3 IOS UP TO 8K SUBS W/LAWFUL INTERCEPT 3DES
<b>S10KK9ZU-12307XI=</b>	Cisco 10000 Series IOS LAWFUL INTERCEPT/SECURED SHELL 3DES	S103K9ZU-12231SB=	Cisco 10K PRE3 IOS UP TO 8K SUBS W/LAWFUL INTERCEPT 3DES
<b>S10KZ11A-12307XI</b>	Cisco 10000 Series IOS BROADBAND ROUTER 8K	S103Z11-12231SB	Cisco 10K PRE3 IOS UP TO 8K SUBSCRIBERS
<b>S10KZ11A-12307XI=</b>	Cisco 10000 Series IOS BROADBAND ROUTER 8K	S103Z11-12231SB=	Cisco 10K PRE3 IOS UP TO 8K SUBSCRIBERS

### Product Migration Options

All customers should migrate to Cisco IOS Software Release 12.2(31)SB10 or later. The recommended replacement for the Cisco IOS Software Release 12.3(7)XI on the Cisco 10008 Router is Cisco IOS Software Release 12.2(31)SB10 on the Cisco 10008 Router. The new Cisco IOS Software offers compatibility with the existing software and many new features, including high availability with stateful switchover (SSO) and in-service software upgrade (ISSU). The Service Selection Gateway (SSG) feature set in 12.3(7)XI is replaced by the comparable Intelligent Service Gateway (ISG) feature set in 12.2(31)SB10.

### For More Information

For more information about the Cisco End-of-Life Policy, go to:  
[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to:  
<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV  
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0805R)