

End-of-Sale and End-of-Life Announcement for the Cisco 12000 Series Engine 1 8-Port Fast Ethernet Line Card

1096, Amended

Cisco® announces the end-of-sale and end-of life dates for the Cisco 12000 Series Engine 1 8-Port Fast Ethernet Line Card. The last day to order the affected product(s) is April 7, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Customers are encouraged to migrate to the Cisco 12000 Series Engine 5 8-Port Fast Ethernet Shared Port Adapter (SPA) to be used with the Cisco 12000 SPA Interface Processors (part numbers 12000-SIP-401, 12000-SIP-501, or 12000-SIP-601.) Table 2 provides relevant information for migrating to the replacement product.

Table 1. End-of-Life Milestones and Dates for the Cisco 12000 Series Engine 1 8-Port Fast Ethernet Line Card

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	April 7, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 7, 2007
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 7, 2007
End of SW Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 6, 2010
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	April 6, 2008
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 6, 2008
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	July 6, 2011
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 5, 2012

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
---------------------------------	---------------------	---------------------------------	---------------------------------

8FE-TX-RJ45-B	8-port 100baseTX, RJ45 connector type, version B	SPA-8XFE-TX	8-port 10/100 Ethernet Shared Port Adapter with RJ-45
8FE-TX-RJ45-B=	8-port 100baseTX, RJ45 connector type, version B	SPA-8XFE-TX=	8-port 10/100 Ethernet Shared Port Adapter with RJ-45

Product Migration Options

Customers are encouraged to migrate to the Cisco 12000 Series Engine 5 8-Port Fast Ethernet Shared Port Adapter. Information about this product can be found at

http://www.cisco.com/en/US/products/ps6267/products_data_sheet0900aecd80350cd7.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the Cisco 12000 Series Engine 1 8-Port Fast Ethernet Line Card through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to <http://www.cisco.com/go/eos>.

For More Information

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices

CCDE, CCVP, Cisco EEM, Cisco StadiumMotion, the Cisco logo, COE, and Welcome to the Human Network are trademarks. Changing the Way We Work, Live, Play and Learn is a service mark, and Access Registrar, Aronix, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco IPsec, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, Enterprise/Solver Ether-Channel, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Presence, FrameShare, GeoDrive, HomeLink, Internet Explorer, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, IQ Net, iQ Ready, iQ Ready: Seeboard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Netwitness, Networking Academy, Network Registrar, PCNow, PIX, PowerPanel, ProCommand, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Power to Increase Your Return, Unified, Unified Communications, UnifiedPush, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of this word, partner, does not imply a partnership relationship between Cisco and any other company. ©2007 [R]