

End-of-Sale and End-of-Life Announcement for the 1-Port ADSL-over-POTS WAN Interface Card (WIC-1ADSL)

EOL6491

Cisco® announces the end-of-sale and end-of life dates for the 1-Port ADSL-over-POTS WAN Interface Card (WIC-1ADSL). The last day to order the affected product(s) is November 28, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the WIC-1ADSL

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 28, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	November 28, 2009
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	February 27, 2010
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	November 28, 2010
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	November 28, 2010
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	November 28, 2010
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 26, 2014
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 27, 2014

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
WIC-1ADSL	1-port ADSL WAN Interface Card	HWIC-1ADSL	1-port ADSLoPOTS HWIC
WIC-1ADSL=	1-port ADSL WAN Interface Card	HWIC-1ADSL=	1-port ADSLoPOTS HWIC
CISCO1841-ADSL	1841 ADSLoPOTS Bdle,IP Broadband,32FL/128DR	CISCO1841-ADSL2	1841 bundle, HWIC-1ADSL, IP BB, 32F/128D
CISCO2801-ADSL/K9	2801 DSL Bundle,WIC-1ADSL(ADSLoPOTS),SP Serv,64F/192D	CISCO2801-ADSL2/K9	2801 bundle, HWIC-1ADSL, SP Svcs, 64F/192DR

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO2811-ADSL/K9	2811 with WIC-1ADSL (ADSLoPOTs), SP Ser IOS, 64F/256D	CISCO2811-ADSL2/K9	2811 bundle, HWIC-1ADSL, SP Svcs, 64FL/256DR

Product Migration Options

Customers are encouraged to migrate to the 1-Port ADSL-over-POTS High-Speed WAN Interface Card (HWIC-1ADSL). Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product_data_sheet0900aecd80394b7e_ps5853_Products_Data_Sheet.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the 1-Port ADSL-over-POTS WAN Interface Card through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the HWIC-1ADSL, visit

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product_data_sheet0900aecd80394b7e_ps5853_Products_Data_Sheet.html, or contact your local account representative.

To request information about the HWIC-1ADSL, send an e-mail to cs-dsl-cpe@cisco.com.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0807R)