

Retraction of End-of-Sale and End-of-Life Announcement for the Cisco 1-Port Symmetric High-Bit-Rate DSL WAN Interface Card and Associated Bundles for Cisco 1841 and 28xx ISR Routers

EOL6788 – Amended

Cisco has retracted the EOS and EOL announcement for the Cisco 1-Port G.SHDSL WAN Interface Card (part number WIC-1SHDSL-V3) WAN Interface Card and Associated Bundles for Cisco 1841 and 28xx ISR Routers.

Cisco 1-Port Symmetric High-Bit-Rate DSL WAN Interface Card and Associated Bundles for Cisco 1841 and 28xx ISR Routers have been restored to their supported status. The products impacted by this announcement are in Table 1 below.

Table 1. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
C2801-SHDSL-V3/K9	2801 DSL bundle, WIC-1SHDSL-V3 (4-wire), SP Svcs, 64F/192D
C2811-SHDSL-V3/K9	2811 DSL bundle, WIC-1SHDSL-V3 (4-wire), SP Svcs, 64F/256D
CISCO1841-SHDSL-V3	1841 DSL bundle, WIC-1SHDSL-V3 (4-wire), IP Broadband, 32F/128D
WIC-1SHDSL-V3	1-port G.shdsl WIC with Four Wire Support (system)
WIC-1SHDSL-V3=	1-port G.shdsl WIC with Four Wire Support (spare)

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco trademarks can be found at www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (10020)