

End-of-Sale and End-of-Life Announcement for the Cisco 2600/3600/3700 Series ATM OC-3 155-Mbps Network Modules

EOL6211

Cisco® announces the end-of-sale and end-of life dates for the Cisco 2600/3600/3700 Series ATM OC-3 155-Mbps Network Modules. The last day to order the affected product(s) is April 30, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco 2600/3600/3700 Series ATM OC-3 155-Mbps Network Modules

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 31, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 30, 2008
Last Ship Date HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 29, 2008
End of Routine Failure Analysis Date HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	April 30, 2009
End of New Service Attachment Date HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 30, 2009
End of Service Contract Renewal Date HW	The last date to extend or renew a service contract for the product.	July 26, 2012
Last Date of Support HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 29, 2013

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
NM-1A-OC3MM	One-port ATM OC-3 Multimode NM for 2691,3600,3725	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3MM=	One-port ATM OC-3 Multimode NM for 2691,3600, 3725	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3MM-EP	1-Port OC-3 Multimode ATM Enhanced performance NM for 3745	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
NM-1A-OC3MM-EP=	1-Port OC-3 Multimode ATM Enhanced performance NM for 3745	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SMI	One-port ATM OC-3 Singlemode Inter Reach NM 2691,3600,3725	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SML=	One-port ATM OC-3 Singlemode Inter Reach NM 2691,3600,3725	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SMI-EP	1-Port OC-3 ATM Enhanced perf Singlemode Int Reach NM 3745	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SMI-EP=	1-Port OC-3 ATM Enhanced perf Singlemode Int Reach NM 3745	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SML	One-port ATM OC-3 Singlemode Long Reach NM 2691,3600,3725	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SML=	One-port ATM OC-3 Singlemode Long Reach NM 2691,3600,3725	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SML-EP	1-Port OC-3 ATM Enhanced Perf Singlemode Long NM 3745	NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3SML-EP=	1-Port OC-3 ATM Enhanced Perf Singlemode Long NM 3745	NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot

Product Migration Options

Customers are encouraged to migrate to the Cisco 3800 Series ATM OC-3 Network Module.

Information about this product can be found at

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product_data_sheet0900aecd80300024.html.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to <http://cisco.com/go/remarketing>.

For More Information

For more information about the Cisco 3800 Series ATM OC-3 Network Module, visit

http://www.cisco.com/en/US/prod/collateral/routers/ps5855/product_data_sheet0900aecd80300024.html, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to

http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0689

Asia Pacific Headquarters
Cisco Systems, Inc.
155 Robinson Road
#29-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Heerlenbergpark
Heerlenbergweg 13-19
1101 CH Amsterdam
The Netherlands
www.europe.cisco.com
Tel: +31 0 20 620 0791
Fax: +31 0 20 657 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Ridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPK, Catalyst, CCNA, CCDF, CCIE, CCR, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fax, Step, Follow Me, Browning, ForceShare, Go2Drive, HomeLink, Internet Quotient, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, IQ Not, Roadnote, Scorecard, iQuickStudy, iSignStream, iInlays, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, ScriptShare, SMARTnet, SsookWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (9705R)