

End-of-Sale and End-of-Life Announcement for the Select Cisco 888 Integrated Services Routers and Select WAN/LAN modules and cables for ISR G1

EOL10324 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Select Cisco 888 Integrated Services Routers and Select WAN/LAN modules and cables for ISR G1. The last day to order the affected product(s) is October 1, 2015. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Select Cisco 888 Integrated Services Routers and Select WAN/LAN modules and cables for ISR G1

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	April 2, 2015
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	October 1, 2015
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 30, 2015
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	September 30, 2016
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	September 30, 2016
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	September 30, 2016
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	December 27, 2019
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	September 30, 2020

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
CISCO888-K9	Cisco888 G.SHDSL Sec Router w/ ISDN B/U	C888-K9	Cisco 880 Series Integrated Services Routers	-
CISCO888-SEC-K9	Cisco888 G.SHDSL Sec Router w/ ISDN B/U w/ Adv IP Services	C888-K9	Cisco 880 Series Integrated Services Routers	-

End-of-Sale Product Part Number	Product Description
ACS-2500ASYN	Auxiliary/Console Port Cable Kit
ACS-IAD2435RM-19	IAD2435 19 Rack Bracket
CAB-ADPT4P-75-120	4 pack 75-120 Ohm adapter cables
CAB-E1-RJ45NT	E1 Cable RJ45 to RJ45 NT
CAB-E1-RJ45NT=	Spare E1 Cable RJ45 to RJ45 NT
CAB-E1-RJ45RJ45	E1 Cable RJ45 to RJ45
CAB-E1-RJ45RJ45=	Spare E1 Cable RJ45 to RJ45
CAB-E1-RJ45TE	E1 Cable RJ45 to RJ45 TE
CAB-E1-RJ45TE=	Spare E1 Cable RJ45 to RJ45 TE
CAB-E1-RJ45TWIN	E1 Cable RJ45 to Twinax (Balanced)
CAB-E1-RJ45TWIN=	E1 Cable RJ45 to Twinax (balanced), Spare
CAB-OCT-V35-FC	8 Lead Octal Cable and 8 Female V35 DCE Connectors
CAB-OCT-V35-MT	8 Lead Octal Cable and 8 Male V35 DTE Connectors
CAB-T1-RJ45BARE	T1 Cable RJ45 to RJ45 Bare
CAB-T1-RJ45BARE=	T1 Cable RJ45 to RJ45 Bare, Spare
MEM-224-1X128D-U	128MB DRAM Memory for VG224 (Factory Upgrade)
MEM-224-1X64F-U	64MB Flash Memory for VG224 (Factory Upgrade)
MEM-243-1X128F-U	128MB Flash Memory for IAD2430 (Factory Upgrade)
MEM-243-1X64F	64MB Flash Memory for IAD2430 series
MEM-243-2X128D-U	256 (2x128)MB DRAM Memory for IAD2430 ser (Factory Upgrade)
NM-1A-OC3-POM	ATM OC3 module with single POM (SFP) slot
NM-1A-OC3-POM=	ATM OC3 module with single POM (SFP) slot
NM-1A-T3/E3	1-Port T3/E3 ATM network Module
NM-1A-T3/E3=	1-Port T3/E3 ATM network Module
NME-RVPN-G2=	ISR G2 Bundle for Russian VPN and NM-SM-ADPTR

Product Migration Options

There is no replacement available for the Select WAN/LAN Modules and Cables for Cisco Integrated Services Routers (G1) at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Select Cisco 888 Integrated Services Routers and Select WAN/LAN modules and cables for ISR G1 through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)