

## End-of-Sale and End-of-Life Announcement for the Cisco 7304 NSE-100 Network Services Engine

EOL6210

Cisco® announces the end-of-sale and end-of life dates for the Cisco 7304 NSE-100 Network Services Engine. The last day to order the affected product(s) is March 31, 2008. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco 7304 NSE-100 Network Services Engine

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 1, 2007
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 31, 2008
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	June 29, 2008
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	March 31, 2009
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	March 31, 2009
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	June 26, 2012
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	March 30, 2013

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
CISCO7304	4-slot chassis, NSE100, 1 Power Supply, 512MB Memory	CISCO7304-NSE-150	4-slot chassis, NSE-150, 1 Power Supply, 2GB Memory
CISCO7304-CH	Channel bundle:chassis,NSE-100,PWR-AC,MEM512,CFM-254,IOS,FAN	CISCO7304CH-NSE150	Channel bundle:chassis,NSE-150,PWR-AC, IOS IP PLUS,FAN
7300-NSE-100	Cisco 7304 NSE-100 w/512MB SDRAM, 256MB Flsh, (2)GE	7300-NSE-150	Cisco 7304 NSE-150 w/2GB SDRAM, 256MB Flsh, (4)GE
7300-NSE-100=	Cisco 7304 NSE-100 w/512MB SDRAM, 256MB Flsh, (2)GE (Spare)	7300-NSE-150=	Cisco 7304 NSE-150 w/2GB SDRAM, 256MB Flsh, (4)GE

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
7300-NSE-100/2	Redundant Cisco 7304 NSE-100	7300-NSE-150/2	Redundant Cisco 7304 NSE-150 w/2GB SDRAM, 256MB Flash, (4)GE
7300-MEM-512	512MB SDRAM for 7304 NSE-100	N/A	Replaced by NSE150 on-board memory
7300-MEM-512=	512MB SDRAM for 7304 NSE-100, spare	N/A	Replaced by NSE150 on-board memory

## Product Migration Options

Customers are encouraged to migrate to the Cisco 7304 NSE-150 Network Services Engine.

Information about this product can be found at

[http://www.cisco.com/en/US/prod/collateral/routers/ps352/prod\\_bulletin0900aecd8060aac5.html](http://www.cisco.com/en/US/prod/collateral/routers/ps352/prod_bulletin0900aecd8060aac5.html).

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to

<http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through the Cisco Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to <http://cisco.com/go/remarketing>

## For More Information

For more information about the Cisco 7304 NSE-150 Network Services Engine, visit

[http://www.cisco.com/en/US/prod/collateral/routers/ps352/prod\\_bulletin0900aecd8060aac5.html](http://www.cisco.com/en/US/prod/collateral/routers/ps352/prod_bulletin0900aecd8060aac5.html),

or contact your local account representative.

To request information about the Cisco 7304 NSE-150 Network Services Engine, send an e-mail to

[ask-7304-pm@cisco.com](mailto:ask-7304-pm@cisco.com).

For more information about the Cisco End-of-Life Policy, go to

[http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to [http://www.cisco.com/cgi-](http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice)

[bin/Support/FieldNoticeTool/field-notice](http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice)



Americas Headquarters  
Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
[www.cisco.com](http://www.cisco.com)  
Tel: 408 526-4000  
800 353-NETS (6387)  
Fax: 408 527-0889

Asia Pacific Headquarters  
Cisco Systems, Inc.  
155 Robinson Road  
#29-01 Capital Tower  
Singapore 068912  
[www.cisco.com](http://www.cisco.com)  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Europe Headquarters  
Cisco Systems International BV  
Hearsherpark  
Hearshergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
[www.europe.cisco.com](http://www.europe.cisco.com)  
Tel: +31 20 630 620 6/91  
Fax: +31 20 657 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

©2007 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, AirNet, BPK, Catalyst, CCD, CCO, CCIE, CCR, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast, Step, Follow Me Browsing, FormShare, Go to Drive, HomeLink, Internet Quotient, IOS, IPPhone, IPTV, IQ Expertise, the IQ logo, IQ Not Ready, iQ Scorecard, iQuickStudy, iSignStream, iInlays, iMeeting Place, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, ScriptShare, SMARTnet, SsookWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (9705R)