



PRODUCT BULLETIN NO. 2599

NEW SECURITY DEVICE MANAGER BUNDLES FOR THE CISCO 830 SERIES SECURE BROADBAND ROUTER

NEW FEATURES

Cisco Systems® is introducing new security device manager bundles for the Cisco® 830 Series of secure broadband routers.

With these new security device manager bundles, the Cisco 830 Series routers will be bundled with Cisco Security Device Manager (SDM) 2.0. With Cisco SDM 2.0 preloaded on the routers, users can configure router and security functions on the Cisco 830 Series.

The Cisco Router Web Setup (RWS) tool is not included with these bundles. Other Cisco 830 products ship with the Cisco RWS as a simple GUI for router setup, but they do not ship with the Cisco SDM.

AVAILABILITY

The Cisco 830 Series SDM bundles are available now.

ORDERING INFORMATION

Table 1 gives ordering information for the Cisco 830 Series SDM bundles.

Table 1. Ordering Information for Cisco 830 Series SDM Bundles

Part Number	Description
CISCO831-SDM-K9	Cisco 831 Router bundled with Cisco SDM 2.0
CISCO836-SDM-K9	Cisco 836 Router bundled with Cisco SDM 2.0
CISCO837-SDM-K9	Cisco 837 Router bundled with Cisco SDM 2.0

FOR MORE INFORMATION

For more information about the Cisco 830 Series Secure Broadband Router, visit <http://www.cisco.com/go/800>.

MARKETING CONTACTS

Hari Harikrishnan, product manager

E-mail: harikris@cisco.com

Phone: 408 525-3954

Hu, Qing, product manager

E-mail: qinghu@cisco.com

Phone: 408 902-8395

Geir Leirvik, product manager

E-mail: gleirvik@cisco.com

Phone: 47 (0)23 27-3641



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Web site at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2004 Cisco Systems, Inc. All rights reserved. CCIP, CCSP, the Cisco *Powered* Network mark, Cisco Unity, Follow Me Browsing, FormShare, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, Fast Step, GigaStack, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MGX, MICA, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, ScriptShare, SlideCast, SMARTnet, StrataView Plus, Stratm, SwitchProbe, TeleRouter, The Fastest Way to Increase Your Internet Quotient, TransPath, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0402R) 204064_ETMG_KW_09.04

