

End-of-Sale and End-of-Life Announcement for the Cisco Select 8K 1st Gen Products

Contents

Overview	3
End-of-life milestones	3
Product Part Numbers	4
Product migration options	5
For more information	6

Overview

EOL15236 - Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco Select 8K 1st Gen Products. The last day to order the affected product(s) is January 30, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-Life Milestones and Dates for the Cisco Select 8K 1st Gen Products

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	January 31, 2024
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	January 30, 2025
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 1, 2025
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 30, 2026
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	January 30, 2026
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	April 30, 2029
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2030

HW = Hardware OS SW = Operating System Software App. SW = Application Software

The terminal IOS-XR release for below PIDs is 25.3.x. The SW support milestone will follow standard Cisco SW support policy.

Product Part Numbers

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
8201-SYS	Cisco 8201 Chassis w/ 24x400GE QSFP56- DD&12x100GE QSFP28	8201-32FH	Cisco 8200 32x400G QSFPDD 1RU Fixed System w/HBM	-
8202-SYS	Cisco 8202 Chassis w/ 12x400GE QSFP56- DD&60x100GE QSFP28	8201-32FH	Cisco 8200 32x400G QSFPDD 1RU Fixed System w/HBM	-
8800-LC-36FH	Cisco 8800 36x400GE QSFP56-DD Line Card	88-LC0-36FH	Cisco 8800 36x400GE QSFP56-DD Line Card	-
8808-FC	Cisco 8808 Fabric Card	8808-FC0	Cisco 8000 Fabric Cards for 8808	-
8818-FC	Cisco 8818 Fabric Card	8818-FC0	Cisco 8818 Fabric Card	-
8201	Cisco 8201 Chassis w/ 24x400GE QSFP56- DD&12x100GE QSFP28	There is currently no replacement product available for this product.	-	-
8201=	Cisco 8201 Chassis w/ 24x400GE QSFP56- DD&12x100GE QSFP28	There is currently no replacement product available for this product.	-	-
8202	Cisco 8202 Chassis w/ 12x400GE QSFP56- DD&60x100GE QSFP28	There is currently no replacement product available for this product.	-	-
8202=	Cisco 8202 Chassis w/ 12x400GE QSFP56- DD&60x100GE QSFP28	There is currently no replacement product available for this product.	-	-
8808-FC=	Cisco 8808 Fabric Card	There is currently no replacement product available for this product.	-	-
8818-FC=	Cisco 8818 Fabric Card	There is currently no replacement product available for this product.	-	-
8800-LC-36FH=	Cisco 8800 36x400GE QSFP56-DD Line Card	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
FAN-1RU-PI	1RU Fan with Port-side Air Intake	There is currently no replacement product available for this product.	-	-
FAN-1RU-PI=	1RU Fan with Port-side Air Intake	There is currently no replacement product available for this product.	-	-
FAN-1RU-PE	1RU Fan with Port-side Exhaust	There is currently no replacement product available for this product.	-	-
FAN-1RU-PE=	1RU Fan with Port-side Exhaust	There is currently no replacement product available for this product.	-	-
FAN-2RU-PI	2RU Fan with Port-side Air Intake	There is currently no replacement product available for this product.	-	-
FAN-2RU-PI=	2RU Fan with Port-side Air Intake	There is currently no replacement product available for this product.	-	-

Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

https://www.cisco.com/web/partners/incentives and promotions/tmp.html.

Customers may be able to continue to purchase the Cisco Select 8K 1st Gen Products through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: https://www.cisco.com/go/eos.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to: https://www.cisco.com/c/en/us/products/eos-eol-policy.html.

For more information about the Cisco Product Warranties, go to: https://www.cisco.com/c/en/us/products/warranty-listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to: https://cway.cisco.com/mynotifications.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore **Europe Headquarters**Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA 07/25