



## End-of-Sale and End-of-Life Announcement for the Cisco RV315W Wireless-N VPN Router

EOL11310-Amended

Cisco announces the end-of-sale Cisco RV315W Wireless-N VPN Router. The last day to order the affected product(s) is February 13, 2017. Customers will continue to receive phone support from the Cisco Small Business Support Center (SBSC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active product warranties, support will be available as stated in the product warranty terms and conditions.

**Table 1.** End-of-Life Milestones and Dates for the Cisco RV315W Wireless-N VPN Router

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	November 14, 2016
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 13, 2017
<b>End of Phone Support: HW</b>	The last date to receive phone support as part of the product warranty. After this date, all phone support services for the product are available with additional charges or support fees. In some cases, support may not be available.	February 13, 2018
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 14, 2017
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	February 13, 2018
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete <sup>1</sup> . Warranty duration is based on product ship dates; refer to warranty terms and conditions for details.	February 28, 2022

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
RV315W-A-K9-AU	Cisco RV315W Broadband Wireless N VPN Firewall	RV130W-A-K9-AU	Cisco RV130 Multifunction Wireless-N VPN Router	-
RV315W-E-K9-EU	Cisco RV315W Broadband Wireless N VPN Firewall	RV130W-E-K9-G5	Cisco RV130 Multifunction Wireless-N VPN Router	-
RV315W-E-K9-UK	Cisco RV315W Broadband Wireless N VPN Firewall	RV130W-E-K9-G5	Cisco RV130 Multifunction Wireless-N VPN Router	-

---

## Product Migration Options

Customers are encouraged to migrate to the Cisco RV130W Wireless-N Multifunction VPN Router. Information about this product can be found at: <https://www.cisco.com/c/en/us/products/routers/rv130w-wireless-n-multifunction-vpn-router/index.html>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[https://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more Information about the Cisco RV130W Wireless-N Multifunction VPN Router, visit <https://www.cisco.com/c/en/us/products/routers/rv130w-wireless-n-multifunction-vpn-router/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [https://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](https://www.cisco.com/en/US/products/products_end-of-life_policy.html).

\*\*For more information about the Cisco Product Warranties, go to: [https://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](https://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to: <https://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: [https://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](https://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)