



END-OF-LIFE NOTICE, NO. 1025

CISCO SECURE INTRUSION DETECTION SYSTEM (FORMERLY NETRANGER) PRODUCT PART NUMBER CHANGE

INTRODUCTION

This Product Bulletin covers the issues associated with a change of product part numbers for the Cisco® Secure Intrusion Detection System. This part number change is effective January 26, 2000.

RATIONALE

The part numbering scheme is being changed to reflect:

1. The product name change from NetRanger to the Cisco Secure Intrusion Detection System.
2. The change from PII-400 to PIII-600 CPUs due to component end-of-life and the addition of more RAM.

DISCONTINUED AND REPLACEMENT PRODUCT PART NUMBERS

Table 1 lists the discontinued products and their replacements.

Table 1. Discontinued and Replacement Product Part Numbers

Previous Product Number	Description	Replacement Product Number
NRS-2E-DM	Cisco Secure IDS Ethernet Sensor	IDS-4220-E
NRS-TR-DM	Cisco Secure IDS Token Ring Sensor	IDS-4220-TR
NRS-2FE-DM	Cisco Secure IDS Fast Ethernet Sensor	IDS-4230-FE
NRS-SFDDI-DM	Cisco Secure IDS SAS FDDI Sensor	IDS-4230-SFDDI
NRS-DFDDI-DM	Cisco Secure IDS DAS FDDI Sensor	IDS-4230-DFDDI
NRD-DIR	Cisco Secure IDS Director Software	IDS-DIR
NRS-DM-U	Upgrade of CSIDS Sensor SW without SW App Sort	IDS-SW-U
NRD-DIR-U	Upgrade of CSIDS Director SW without SW App Sort	IDS-DIR-U
CON-SNT-NRS-2E-DM	Cisco Secure IDS SMARTnet Maintenance—IDS-422X-E	CON-SNT-IDS-E
CON-SNTE-NRS-2E-DM	Cisco Secure IDS Enhanced SMARTnet Maintenance—IDS-422X-E	CON-SNTE-IDS-E
CON-SNTP-NRS-2E-DM	Cisco Secure IDS Premium SMARTnet Maintenance—IDS-422X-E	CON-SNTP-IDS-E
CON-OS-NRS-2E-DM	Cisco Secure IDS Onsite Standard Maintenance—IDS-422X-E	CON-OS-IDS-E
CON-OSE-NRS-2E-DM	Cisco Secure IDS Onsite Enhanced Maintenance—IDS-422X-E	CON-OSE-IDS-E
CON-OSP-NRS-2E-DM	Cisco Secure IDS Onsite Premium Maintenance—IDS-422X-E	CON-OSP-IDS-E
CON-SNT-NRS-TR-DM	Cisco Secure IDS SMARTnet Maintenance—IDS-422X-TR	CON-SNT-IDS-TR
CON-SNTE-NRS-TR-DM	Cisco Secure IDS Enhanced SMARTnet Maintenance—IDS-422X-TR	CON-SNTE-IDS-TR
CON-SNTP-NRS-TR-DM	Cisco Secure IDS Premium SMARTnet Maintenance—DS-422X-TR	CON-SNTP-IDS-TR

Previous Product Number	Description	Replacement Product Number
CON-OS-NRS-TR-DM	Cisco Secure IDS Onsite Standard Maintenance—IDS-422X-TR	CON-OS-IDS-TR
CON-OSE-NRS-TR-DM	Cisco Secure IDS Onsite Enhanced Maintenance—IDS-422X-TR	CON-OSE-IDS-TR
CON-OSP-NRS-TR-DM	Cisco Secure IDS Onsite Premium Maintenance—IDS-422X-TR	CON-OSP-IDS-TR
CON-SNT-NRS-FE-DM	Cisco Secure IDS SMARTnet Maintenance—IDS-423X-FE	CON-SNT-IDS-FE
CON-SNTE-NRS-FE-DM	Cisco Secure IDS Enhanced SMARTnet Maintenance—IDS-423X-FE	CON-SNTE-IDS-FE
CON-SNTP-NRS-FE-DM	Cisco Secure IDS Premium SMARTnet Maintenance—IDS-423X-FE	CON-SNTP-IDS-FE
CON-OS-NRS-FE-DM	Cisco Secure IDS Onsite Standard Maintenance—IDS-423X-FE	CON-OS-IDS-FE
CON-OSE-NRS-FE-DM	Cisco Secure IDS Onsite Enhanced Maintenance—IDS-423X-FE	CON-OSE-IDS-FE
CON-OSP-NRS-FE-DM	Cisco Secure IDS Onsite Premium Maintenance—IDS-423X-FE	CON-OSP-IDS-FE
CON-SNT-NRS-FD-DM	Cisco Secure IDS SMARTnet Maintenance—SFDDI or DFDDI	CON-SNT-IDS-FD
CON-SNTE-NRS-FD-DM	Cisco Secure IDS Enhanced SMARTnet Maintenance—SFDDI or DFDDI	CON-SNTE-IDS-FD
CON-SNTP-NRS-FD-DM	Cisco Secure IDS Premium SMARTnet Maintenance—SFDDI or DFDDI	CON-SNTP-IDS-FD
CON-OS-NRS-FD-DM	Cisco Secure IDS Onsite Standard Maintenance—NRS-SFDDI- or NRS-DFDDI	CON-OS-IDS-FD
CON-OSE-NRS-FD-DM	Cisco Secure IDS Onsite Enhanced Maintenance—NRS-SFDDI- or NRS-DFDDI	CON-OSE-IDS-FD
CON-OSP-NRS-FD-DM	Cisco Secure IDS Onsite Premium Maintenance—NRS-SFDDI- or NRS-DFDDI	CON-OSP-IDS-FD
CON-SAU-NRD-DIR	Cisco Secure IDS Director Software SAU Service	CON-SAU-IDS-DIR
CON-SAS-NRD-DIR	Cisco Secure IDS Director Software SAS Service	CON-SAS-IDS-DIR

ASSISTANCE

For specific orderability questions, contact your Customer Service Representative.



Corporate Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

