

## End-of-Sale and End-of-Life Announcement for the Select Cisco 2-, 4-, and 8-GB DDR3-1066MHz Memory DIMMs for B-Series and C-Series Servers

EOL7261 — Amended

Cisco announces the end-of-sale and end-of life dates for the Select Cisco 2-, 4-, and 8-GB DDR3-1066MHz Memory DIMMs for B-Series and C-Series Servers. The last day to order the affected product(s) is February 4, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Select Cisco 2-, 4-, and 8-GB DDR3-1066MHz Memory DIMMs for B-Series and C-Series Servers

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	November 5, 2010
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	February 4, 2011
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 5, 2011
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	February 4, 2012
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	February 4, 2012
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	May 2, 2015
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 29, 2016

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N01-M302GA1	2GB DDR3-1066MHz RDIMM/PC3-8500/single rank 1Gb DRAMs	N01-M302GB1	2GB DDR3-1333MHz RDIMM/PC3-10600/single rank 1Gb DRAMs	--
N01-M302GA1=	2GB DDR3-1066MHz RDIMM/PC3-8500/single rank 1Gb DRAMs	N01-M302GB1=	2GB DDR3-1333MHz RDIMM/PC3-10600/single rank 1Gb DRAMs	--
N01-M304GA1	4GB DDR3-1066MHz RDIMM/PC3-8500/dual rank 1Gb DRAMs	N01-M304GB1	4GB DDR3-1333MHz RDIMM/PC3-10600/dual rank 1Gb DRAMs	--

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N01-M304GA1=	4GB DDR3-1066MHz RDIMM/PC3-8500/dual rank 1Gb DRAMs	N01-M304GB1=	4GB DDR3-1333MHz RDIMM/PC3-10600/dual rank 1Gb DRAMs	--
N01-M308GA1	8GB DDR3-1066MHz RDIMM/PC3-8500/quad rank 1Gb DRAMs	N01-M308GB2	8GB DDR3-1333MHz RDIMM/PC3-10600/dual rank 2Gb DRAMs	--
N01-M308GA1=	8GB DDR3-1066MHz RDIMM/PC3-8500/quad rank 1Gb DRAMs	N01-M308GB2=	8GB DDR3-1333MHz RDIMM/PC3-10600/dual rank 2Gb DRAMs	--

## Product Migration Options

Customers are encouraged to migrate to the appropriate Cisco DDR3-1333MHz RDIMM/PC3-10600 Memory DIMM as indicated in Table 2. Information about this product can be found at:

<http://www.cisco.com/en/US/products/ps10280/index.html>.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html)

## For More Information

For more information about the Cisco DDR3-1333MHz RDIMM/PC3-10600 Memory DIMMs, visit <http://www.cisco.com/en/US/products/ps10280/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html)

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml)

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)

Printed in USA

C51-642282-01 03/11