



End-of-Sale and End-of-Life Announcement for the Cisco UCS 5108 Blade Server Chassis N20-C6508

EOL11134 - Amended

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS 5108 Blade Server Chassis N20-C6508. The last day to order the affected product(s) is December 1, 2016. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco UCS 5108 Blade Server Chassis N20-C6508

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	September 1, 2016
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 1, 2016
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 1, 2017
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 1, 2017
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 1, 2017
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	February 26, 2021
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	November 30, 2021

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N20-C6508	UCS 5108 Blade Svr AC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-AC2	UCS 5108 Blade Server AC2 Chassis, 0 PSU/8 fans/0 FEX	-
N20-C6508-CH2	DISTI:UCS 5108 Blade Svr AC Chassis/0 PSU/8 fan/0 fab extdr	UCSB-5108-AC2-CH	DISTI: UCS 5108 Blade Server AC2 Chassis, 0 PSU/8 fans/0 FEX	-
N20-C6508-UPG	UCS 5108 Blade Svr AC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-AC2-UPG	UCS 5108 Blade Server AC2 Chassis/0 PSU/8 fans/0 FEX	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
N20-C6508=	UCS 5108 Blade Svr AC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-AC2=	UCS 5108 Blade Server AC2 Chassis/0 PSU/8 fans/0 FEX	-
UCS-EZ-INFRA-CHSS	UCS EZ BUN 5108 Blade Svr AC Chassis, 4PS, 2 IOM	UCSB-5108-AC2-UPG	UCS 5108 Blade Server AC2 Chassis/0 PSU/8 fans/0 FEX	-
UCS-EZ-VXI-ICA	INVALID SKU - NOT TO BE USED	There is currently no replacement product available for this product.	-	This PID was moved from EOL11422 to match the support timelines of base PID.
UCS-EZ-VXI-PCOIP	INVALID SKU - NOT TO BE USED	There is currently no replacement product available for this product.	-	This PID was moved from EOL11422 to match the support timelines of base PID.
UCS-SP-INFRA-CHSS	UCS SP BASE 5108 Blade Svr AC Chassis	UCS-SP-5108-AC	UCS SP Select 5108 AC2 Chassis w/2208 IO, 4x SFP cable 3m	-
UCS-SPM-CHSS-T	UCS SPM BASE 5108 Blade Svr AC Chassis with Blades	See the Product Migration Options section below for detailed information on replacing this product.	-	-
UCSB-5108-DC	UCS 5108 Blade DC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-DC2	UCS 5108 Blade Server DC2 Chassis/0 PSU/8 fans/0 FEX	-
UCSB-5108-DC-UPG	UCS 5108 Blade DC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-DC2-UPG	UCS 5108 Blade Server DC2 Chassis/0 PSU/8 fans/0 FEX	-
UCSB-5108-DC-UPG	UCS 5108 Blade DC Chassis/0 PSU/8 fans/0 fabric extender	UCSB-5108-DC2=	UCS 5108 Blade Server DC2 Chassis/0 PSU/8 fans/0 FEX	-

Product Migration Options

Customers are encouraged to migrate to the Cisco UCS 5108 Blade Server Chassis. Information about this product can be found at: <http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-5100-series-blade-server-chassis/index.html>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more Information about the Cisco UCS 5108 Blade Server Chassis, visit <http://www.cisco.com/c/en/us/products/servers-unified-computing/ucs-5100-series-blade-server-chassis/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)