

End-of-Sale and End-of-Life Announcement for the 3.5-Inch Drives for the Cisco UCS C200 M2 High-Density Rack Server and Cisco UCS C210 M2 General-Purpose Rack Server & Other Accessories for the Cisco UCS C250 M2 Extended-Memory Rack-Mount Server

EOL8832

Cisco announces the end-of-sale and end-of life dates for the 3.5-Inch Drives for the Cisco UCS C200 M2 High-Density Rack Server and Cisco UCS C210 M2 General-Purpose Rack Server & Other Accessories for the Cisco UCS C250 M2 Extended-Memory Rack-Mount Server. The last day to order the affected product(s) is December 28, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the 3.5-Inch Drives for the Cisco UCS C200 M2 High-Density Rack Server and Cisco UCS C210 M2 General-Purpose Rack Server & Other Accessories for the Cisco UCS C250 M2 Extended-Memory Rack-Mount Server

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 28, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 28, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 28, 2013
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	December 28, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 28, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	March 25, 2017
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 31, 2017

 $\mbox{HW = Hardware} \qquad \mbox{OS SW = Operating System Software} \quad \mbox{App. SW = Application Software} \\$

 Table 2.
 Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
R200-D1TC03	Gen 2 1TB SAS 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D1TC03=	Gen 2 1TB SAS 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D2TC03	2TB SAS 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D2TC03=	2TB SAS 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D300GB03	Gen 2 300GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D300GB03=	Gen 2 300GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D450GB03	450GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D450GB03=	450GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D500GCSATA03	Gen 2 500GB SATA 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R200-D500GCSATA03=	Gen 2 500GB SATA 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
R250-RSRCDFH=	PCIe Full Height riser card for UCS C250 Rack Server	There is currently no replacement product available for this product.		
UCS-HDD-3TI1F202	3TB SAS 3Gb 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
UCS-HDD-3TI1F202=	3TB SAS 3Gb 7.2K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
UCS-HDD600GI2F201	600GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
UCS-HDD600GI2F201=	600GB SAS 15K RPM 3.5in HDD/hot plug/C200 drive sled	There is currently no replacement product available for this product.		
UCS-MKIT-164RX-C	Mem kit for UCS-MR- 2X164RX-C	UCS-MKIT-164RX-D	Mem kit for UCS-MR- 2X164RX-D	_
UCS-MKIT-164RX-C=	Mem kit for UCS-MR- 2X164RX-C	UCS-MKIT-164RX-D=	Mem kit for UCS-MR- 2X164RX-D	_
UCS-MR-2X164RX-C	2X16GB DDR3-1333-MHz RDIMM/PC3-10600/quad rank/x4/1.35v	UCS-MR-2X164RX-D	2X16GB NHS DDR3-1333- MHz RDIMM/PC3- 10600/quad rank/x4/1.35v	_
UCS-MR-2X164RX-C=	2X16GB DDR3-1333-MHz RDIMM/PC3-10600/quad rank/x4/1.35v	UCS-MR-2X164RX-D=	2X16GB NHS DDR3-1333- MHz RDIMM/PC3- 10600/quad rank/x4/1.35v	_

Product Migration Options

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about cisco takeback recycling.html

For More Information

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: http://www.cisco.com/web/feeds/products/end of life rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA C51-717531-00 09/12