

End-of-Sale and End-of-Life Announcement for the Cisco Select UCS Accessories



Contents

| | |
|---------------------------|---|
| Overview | 3 |
| End-of-life milestones | 3 |
| Product part numbers | 3 |
| Product migration options | 7 |
| For more information | 7 |

Overview

EOL13364

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select UCS Accessories. The last day to order the affected product(s) is June 12, 2020. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select UCS Accessories

| Milestone | Definition | Date |
|--------------------------------------|---|----------------|
| End-of-Life Announcement Date | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public. | March 13, 2020 |
| End-of-Sale Date Accessory | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | June 12, 2020 |
| Last Ship Date Accessory | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | June 12, 2020 |

Product part numbers

Table 2. Product part numbers affected by this announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|---|---|---------------------------------|------------------------|
| UCS-RAID-BBU= | BBU09 for 9266 | There is currently no replacement product available for this product. | - | - |
| UCSC-LBBU02= | Battery back unit for C200 LFF and SFF M2 | There is currently no replacement product available for this product. | - | - |
| HX-GPU-M60 | NVIDIA M60 PCIE 300W 16GB | There is currently no replacement product available for this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| HX-GPU-M60= | UCS Rack Server M60 GPU HW - GRID 2.0 SW req d for VDI | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-M60 | NVIDIA M60 PCIE 300W 16GB | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-M60= | UCS Rack Server M60 GPU HW - GRID 2.0 SW req d for VDI | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-M60-CH | Disti UCS Rack Server M60 GPU HW - GRID 2.0 SW req d for VDI | There is currently no replacement product available for this product. | - | - |
| UCSB-CBAF-B420-M4= | Air Baffle Replacement Kit for B420 M4 Server | There is currently no replacement product available for this product. | - | - |
| UCS-220CBLMR4 | C220 M4 RAID controller cable (1) for 4HDD bckpln chassis | There is currently no replacement product available for this product. | - | - |
| UCS-220CBLMR4= | C220 M4 RAID controller cable (1) for 4HDD bckpln chassis | There is currently no replacement product available for this product. | - | - |
| UCS-SA-BD-FI6332 | (Not sold standalone) UCS 6332 1RU FI/No PSU/32 QSFP+ | There is currently no replacement product available for this product. | - | - |
| UCSC-LBBU02 | Battery back unit for C200 LFF and SFF M2 | There is currently no replacement product available for this product. | - | - |
| UCS-SL-CPA4-H | UCS BD HIPERF 2x6332,8xC220M4S w/2xE52680v4,256G,8x960GB SSD | There is currently no replacement product available for this product. | - | - |
| UCS-SL-CPA4-P3 | UCS BD PERF 2x6332,16xC240M4S w/2xE52680v4,256G,24x1.8TB HDD | There is currently no replacement product available for this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|---|---|------------------------------------|------------------------|
| HX-GPU-7150X2 | AMD Firepro 7150x2 | There is currently no replacement product available for this product. | - | - |
| HX-GPU-7150X2= | AMD Firepro 7150x2 | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-7150X2 | AMD Firepro 7150x2 | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-7150X2= | AMD Firepro 7150x2 | There is currently no replacement product available for this product. | - | - |
| HX-GPU-V340 | AMD Radeon Pro V340, 2X16GB, 300W | There is currently no replacement product available for this product. | - | - |
| HX-GPU-V340= | AMD Radeon Pro V340, 2X16GB, 300W | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-V340 | AMD Radeon Pro V340, 2X16GB, 300W | There is currently no replacement product available for this product. | - | - |
| UCSC-GPU-V340= | AMD Radeon Pro V340, 2X16GB, 300W | There is currently no replacement product available for this product. | - | - |
| UCS-HD8T7KL4KN | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | UCS-HD8T7K4KAN | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| HX-HD8T7KL4KN | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | HX-HD8T7K4KAN | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCS-HD8T7KL4KN= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | UCS-HD8T7K4KAN= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| HX-HD8T7KL4KN= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | HX-HD8T7K4KAN= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCSC-F-S32002 | UCS Rack PCIe Storage 3200GB SanDisk SX350 Medium Endurance | There is currently no replacement product available for this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|---|---|--|------------------------|
| UCSC-F-S32002= | UCS Rack PCIe Storage 3200GB SanDisk SX350 Medium Endurance | There is currently no replacement product available for this product. | - | - |
| UCS-SP-HD-8T | SP 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | There is currently no replacement product available for this product. | - | - |
| UCS-S3260-8TBRR | UCS S3260 8TB NL-SAS 7.2K UE10 HDD rear with HDD Carrier | UCS-S3260-HD8TARR | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCS-S3260-8TBRR= | UCS S3260 8TB NL-SAS 7.2K UE10 HDD rear with HDD Carrier | UCS-S3260-HD8TARR= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCS-S3260-HD8TB | UCS S3260 8TB NL-SAS 7.2K UE10 HDD with HDD Carrier | UCS-S3260-HD8TA | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCS-S3260-HD8TB= | UCS S3260 8TB NL-SAS 7.2K UE10 HDD with HDD Carrier | UCS-S3260-HD8TA= | 8 TB 12G SAS 7.2K RPM LFF HDD (4K) | - |
| UCS-S3260-14HD8 | S3260 1row of 8TB (UE10NL-SAS 7200RPM SAS-3 (14Total: 112TB)) | UCS-S3260-14HD8A | UCS S3260 1row of drives 14x8TB NL-SAS 7200RPM (Total 112TB) | - |
| UCS-S3260-28HD8 | S3260 2row of 8TB (UE10NL-SAS 7200RPM SAS-3 (28Total: 224TB)) | UCS-S3260-28HD8A | UCS S3260 2row of drives 28x8TB NL-SAS 7200RPM (Total 224TB) | - |
| UCS-S3260-42HD8 | S3260 3row of 8TB (UE10NL-SAS 7200RPM SAS-3 (42Total: 336TB)) | UCS-S3260-42HD8A | UCS S3260 3row of drives 42x8TB NL-SAS 7200RPM (Total 336TB) | - |
| UCS-S3260-56HD8 | S3260 4row of 8TB (UE10NL-SAS 7200RPM SAS-3 (56Total: 448TB)) | UCS-S3260-56HD8A | UCS S3260 4row of drives 56x8TB NL-SAS 7200RPM (Total 448TB) | - |
| UCS-S3260-14HD8= | S3260 1row of 8TB (UE10NL-SAS 7200RPM SAS-3 (14Total: 112TB)) | UCS-S3260-14HD8A= | UCS S3260 1row of drives 14x8TB NL-SAS 7200RPM (Total 112TB) | - |

Product migration options

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

https://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For more information

For more information about the Cisco End-of-Life Policy, go to:

https://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

https://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<https://www.cisco.com/cisco/support/notifications.html>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)