

End-of-Sale and End-of-Life Announcement for the Cisco Select UCS M6 and HCI M6 DDR4 Memory

Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	3
For more information	6

Overview

EOL15701

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select UCS M6 and HCI M6 DDR4 Memory. The last day to order the affected product(s) is September 29, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select UCS M6 and HCI M6 DDR4 Memory

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 30, 2025
End-of-Sale Date Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 29, 2025
Last Ship Date Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 28, 2025

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-MP-128GS-B0	Intel Optane Persistent Memory, 128GB, 3200MHz	There is currently no replacement product available for this product.	-	-
UCS-MP-128GS-B0=	Intel Optane Persistent Memory, 128GB, 3200MHz	There is currently no replacement product available for this product.	-	-
UCS-MP-256GS-B0	Intel Optane Persistent Memory, 256GB, 3200MHz	There is currently no replacement product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-MP-256GS-B0=	Intel Optane Persistent Memory, 256GB, 3200MHz	There is currently no replacement product available for this product.	-	-
UCS-MP-512GS-B0	Intel Optane Persistent Memory, 512GB, 3200MHz	There is currently no replacement product available for this product.	-	-
UCS-MP-512GS-B0=	Intel Optane Persistent Memory, 512GB, 3200MHz	There is currently no replacement product available for this product.	-	-
UCS-MR-X32G1RW	32GB RDIMM SRx4 3200 (16Gb)	UCS-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G1RW=	32GB RDIMM SRx4 3200 (16Gb)	UCS-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G1RW-M	32GB 3200MHZ RDIMM (16Gb)	UCS-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G1RW-M=	32GB 3200MHZ RDIMM (16Gb)	UCS-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	UCS-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G2RW=	32GB RDIMM DRx4 3200 (8Gb)	UCS-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-MR-X32G2RW-M	32GB 3200MHZ RDIMM (8Gb)	UCS-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G2RW-M=	32GB 3200MHZ RDIMM (8Gb)	UCS-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G2RW-S	32GB RDIMM DRx4 3200 (8Gb)	UCS-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
UCS-MR-X32G2RW-S=	32GB RDIMM DRx4 3200 (8Gb)	UCS-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
HCI-MR-X32G1RW	32GB RDIMM SRx4 3200 (16Gb)	HCI-MRX32G1RE3	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
HCI-MR-X32G1RW=	32GB RDIMM SRx4 3200 (16Gb)	HCI-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
HCI-MR-X32G2RW	32GB RDIMM DRx4 3200 (8Gb)	HCI-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.
HCI-MR-X32G2RW=	32GB RDIMM DRx4 3200 (8Gb)	HCI-MRX32G1RE3=	32GB DDR5-5600 RDIMM 1Rx4 (16Gb)	These are migration SKUs and not meant for replacement as they are not available on the same parent platform server.

Product migration options

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

<https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html>.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)