

End-of-Sale and End-of-Life Announcement for the Cisco Select UCS M6 and HCI M6 Processors

Contents

Overview	3
End-of-life milestones	3
Product part numbers	3
Product migration options	14
For more information	14

Overview

EOL15703

Cisco announces the end-of-sale and end-of-life dates for the Cisco Select UCS M6 and HCI M6 Processors. The last day to order the affected product(s) is December 30, 2025. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco Select UCS M6 and HCI M6 Processors

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	June 30, 2025
End-of-Sale Date Accessory	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 30, 2025
Last Ship Date Accessory	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 30, 2026

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HCI-CPU-I8358	Intel 8358 2.6GHz/250W 32C/48MB DDR4 3200MHz	HCI-CPU-I8562Y+	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I5318Y=	Intel 5318Y 2.1GHz/165W 24C/36MB DDR4 2933MHz	UCS-CPU-I6542Y=	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I8360YC=	DIST: Intel 8360Y 2.4GHz/250W 36C/54MB DDR4 3200MHz	UCS-CPU-I8568Y+C=	DIST: Intel I8568Y+ 2.3GHz/350W 48C/300MB DDR5 5600MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HCI-CPU-I4316	Intel 4316 2.3GHz/150W 20C/30MB DDR4 2667MHz	HCI-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I5317	Intel 5317 3.0GHz/150W 12C/18MB DDR4 2933MHz	UCS-CPU-I6526Y	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
UCS-CPU-I6348	Intel 6348 2.6GHz/235W 28C/42MB DDR4 3200MHz	UCS-CPU-I6548Y+	Intel I6548Y+ 2.5GHz/250W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I6338N=	Intel 6338N 2.2GHz/185W 32C/48MB DDR4 2667MHz	UCS-CPU-I6538N=	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I8358=	Intel 8358 2.6GHz/250W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+=	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I4314=	Intel 4314 2.4GHz/135W 16C/24MB DDR4 2667MHz	UCS-CPU-I4516Y+=	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I6346C=	DIST1: Intel 6346 3.1GHz/205W 16C/36MB DDR4 3200MHz	UCS-CPU-I6544YC=	DIST1: Intel I6544Y 3.6GHz/270W 16C/45MB DDR5 5200MT/s	-
UCS-CPU-I4310=	Intel 4310 2.1GHz/120W 12C/18MB DDR4 2667MHz	UCS-CPU-I4510=	Intel I4510 2.4GHz/150W 12C/30MB DDR5 4400MT/s	-
UCS-CPU-I5320TC=	DSIT1: Intel 5320T 2.3GHz/150W 20C/30MB DDR4 2933MHz	UCS-CPU-I4516Y+C=	DIST1: Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I6312U=	Intel 6312U 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I5512U=	Intel I5512U 2.1GHz/185W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6326	Intel 6326 2.9GHz/185W 16C/24MB DDR4 3200MHz	UCS-CPU-I6526Y	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HCI-CPU-I6334	Intel 6334 3.6GHz/165W 8C/18MB DDR4 3200MHz	HCI-CPU-I6534	Intel I6534 3.9GHz/195W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I6330	Intel 6330 2.0GHz/205W 28C/42MB DDR4 2933MHz	UCS-CPU-I6530	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
HCI-CPU-I6330	Intel 6330 2.0GHz/205W 28C/42MB DDR4 2933MHz	HCI-CPU-I6530	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
UCS-CPU-I6348C=	DIST1: Intel 6348 2.6GHz/235W 28C/42MB DDR4 3200MHz	UCS-CPU-I6548Y+C=	DIST1: Intel I6548Y+ 2.5GHz/250W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I8351N=	Intel 8351N 2.4GHz/225W 36C/54MB DDR4 2933MHz	UCS-CPU-I6554S=	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I5320	Intel 5320 2.2GHz/185W 26C/39MB DDR4 2933MHz	UCS-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6346	Intel 6346 3.1GHz/205W 16C/36MB DDR4 3200MHz	UCS-CPU-I6544Y	Intel I6544Y 3.6GHz/270W 16C/45MB DDR5 5200MT/s	-
HCI-CPU-I6338T	Intel 6338T 2.1GHz/165W 24C/36MB DDR4 3200MHz	HCI-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
HCI-CPU-I6338	Intel 6338 2.0GHz/205W 32C/48MB DDR4 3200MHz	HCI-CPU-I6538Y+	Intel I6538Y+ 2.2GHz/225W 32C/60MB DDR5 5200MT/s	-
HCI-CPU-I4310	Intel 4310 2.1GHz/120W 12C/18MB DDR4 2667MHz	HCI-CPU-I4510	Intel I4510 2.4GHz/150W 12C/30MB DDR5 4400MT/s	-
UCS-CPU-I5315Y	Intel 5315Y 3.2GHz/140W 8C/12MB DDR4 2933MHz	UCS-CPU-I5515+	Intel I5515+ 3.2GHz/165W 8C/22.5MB DDR5 4800MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
HCI-CPU-I6346	Intel 6346 3.1GHz/205W 16C/36MB DDR4 3200MHz	HCI-CPU-I6544Y	Intel I6544Y 3.6GHz/270W 16C/45MB DDR5 5200MT/s	-
UCS-CPU-I6330N=	Intel 6330N 2.2GHz/165W 28C/42MB DDR4 2667MHz	UCS-CPU-I6538N=	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
HCI-CPU-I5318N	Intel 5318N 2.1GHz/150W 24C/36MB DDR4 2667MHz	HCI-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6326=	Intel 6326 2.9GHz/185W 16C/24MB DDR4 3200MHz	UCS-CPU-I6526Y=	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
HCI-CPU-I6326	Intel 6326 2.9GHz/185W 16C/24MB DDR4 3200MHz	HCI-CPU-I6526Y	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
HCI-CPU-I5315Y	Intel 5315Y 3.2GHz/140W 8C/12MB DDR4 2933MHz	HCI-CPU-I5515+	Intel I5515+ 3.2GHz/165W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I8351NC=	DSITI: Intel 8351N 2.4GHz/225W 36C/54MB DDR4 2933MHz	UCS-CPU-I6554SC=	DISTI: Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I8362	Intel 8362 2.8GHz/265W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I6334=	Intel 6334 3.6GHz/165W 8C/18MB DDR4 3200MHz	UCS-CPU-I6534=	Intel I6534 3.9GHz/195W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I6346=	Intel 6346 3.1GHz/205W 16C/36MB DDR4 3200MHz	UCS-CPU-I6544Y=	Intel I6544Y 3.6GHz/270W 16C/45MB DDR5 5200MT/s	-
UCS-CPU-I6338N	Intel 6338N 2.2GHz/185W 32C/48MB DDR4 2667MHz	UCS-CPU-I6538N	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I5318NC=	DSITI: Intel 5318N 2.1GHz/150W 24C/36MB DDR4 2667MHz	UCS-CPU-I5520+C=	DISTI: Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I5318N	Intel 5318N 2.1GHz/150W 24C/36MB DDR4 2667MHz	UCS-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I5318N=	Intel 5318N 2.1GHz/150W 24C/36MB DDR4 2667MHz	UCS-CPU-I5520+=	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I5320T=	Intel 5320T 2.3GHz/150W 20C/30MB DDR4 2933MHz	UCS-CPU-I4516Y+=	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I5318YC=	DISTI: Intel 5318Y 2.1GHz/165W 24C/36MB DDR4 2933MHz	UCS-CPU-I6542YC=	DISTI: Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I6342	Intel 6342 2.8GHz/230W 24C/36MB DDR4 3200MHz	UCS-CPU-I6542Y	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I4310TC=	DSITI: Intel 4310T 2.3GHz/105W 10C/15MB DDR4 2667MHz	UCS-CPU-I4510TC=	DISTI: Intel I4510T 2.0GHz/115W 12C/30MB DDR5 4400MT/s	-
UCS-CPU-I6336Y=	Intel 6336Y 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I6554S=	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I6342=	Intel 6342 2.8GHz/230W 24C/36MB DDR4 3200MHz	UCS-CPU-I6542Y=	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
HCI-CPU-I4309Y	Intel 4309Y 2.8GHz/105W 8C/12MB DDR4 2667MHz	HCI-CPU-I4509Y	Intel I4509Y 2.6GHz/125W 8C/22.5MB DDR5 4400MT/s	-
HCI-CPU-I6314U	Intel 6314U 2.3GHz/205W 32C/48MB DDR4 3200MHz	HCI-CPU-I6530	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I5320=	Intel 5320 2.2GHz/185W 26C/39MB DDR4 2933MHz	UCS-CPU-I5520+=	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I4316=	Intel 4316 2.3GHz/150W 20C/30MB DDR4 2667MHz	UCS-CPU-I4516Y+=	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I6314U	Intel 6314U 2.3GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6530	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
UCS-CPU-I4310	Intel 4310 2.1GHz/120W 12C/18MB DDR4 2667MHz	UCS-CPU-I4510	Intel I4510 2.4GHz/150W 12C/30MB DDR5 4400MT/s	-
HCI-CPU-I5320T	Intel 5320T 2.3GHz/150W 20C/30MB DDR4 2933MHz	HCI-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
HCI-CPU-I6330N	Intel 6330N 2.2GHz/165W 28C/42MB DDR4 2667MHz	HCI-CPU-I6538N	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I5317C=	DSITI: Intel 5317 3.0GHz/150W 12C/18MB DDR4 2933MHz	UCS-CPU-I6526YC=	DISTI: Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
UCS-CPU-I6338T=	Intel 6338T 2.1GHz/165W 24C/36MB DDR4 3200MHz	UCS-CPU-I5520+=	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
HCI-CPU-I6336Y	Intel 6336Y 2.4GHz/185W 24C/36MB DDR4 3200MHz	HCI-CPU-I6554S	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I6336Y	Intel 6336Y 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I6554S	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I4310T=	Intel 4310T 2.3GHz/105W 10C/15MB DDR4 2667MHz	UCS-CPU-I4510T=	Intel I4510T 2.0GHz/115W 12C/30MB DDR5 4400MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I4314C=	DSITI: Intel 4314 2.4GHz/135W 16C/24MB DDR4 2667MHz	UCS-CPU-I4516Y+C=	DISTI: Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I8362=	Intel 8362 2.8GHz/265W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+=	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I4316C=	DSITI: Intel 4316 2.3GHz/150W 20C/30MB DDR4 2667MHz	UCS-CPU-I4516Y+C=	DISTI: Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
HCI-CPU-I6348	Intel 6348 2.6GHz/235W 28C/42MB DDR4 3200MHz	HCI-CPU-I6548Y+	Intel I6548Y+ 2.5GHz/250W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I6338	Intel 6338 2.0GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6538Y+	Intel I6538Y+ 2.2GHz/225W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I6338T	Intel 6338T 2.1GHz/165W 24C/36MB DDR4 3200MHz	UCS-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6330=	Intel 6330 2.0GHz/205W 28C/42MB DDR4 2933MHz	UCS-CPU-I6530=	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
UCS-CPU-I8351N	Intel 8351N 2.4GHz/225W 36C/54MB DDR4 2933MHz	UCS-CPU-I6554S	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I6314U=	Intel 6314U 2.3GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6530=	Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
UCS-CPU-I4309Y=	Intel 4309Y 2.8GHz/105W 8C/12MB DDR4 2667MHz	UCS-CPU-I4509Y=	Intel I4509Y 2.6GHz/125W 8C/22.5MB DDR5 4400MT/s	-
UCS-CPU-I6338C=	DSITI: Intel 6338 2.0GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6538Y+C=	DISTI: Intel I6538Y+ 2.2GHz/225W 32C/60MB DDR5 5200MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I4310C=	DSITI: Intel 4310 2.1GHz/120W 12C/18MB DDR4 2667MHz	UCS-CPU-I4510C=	DISTI: Intel I4510 2.4GHz/150W 12C/30MB DDR5 4400MT/s	-
UCS-CPU-I6338NC=	DSITI: Intel 6338N 2.2GHz/185W 32C/48MB DDR4 2667MHz	UCS-CPU-I6538NC=	DISTI: Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I6342C=	DISTI: Intel 6342 2.8GHz/230W 24C/36MB DDR4 3200MHz	UCS-CPU-I6542YC=	DISTI: Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I5318Y	Intel 5318Y 2.1GHz/165W 24C/36MB DDR4 2933MHz	UCS-CPU-I6542Y	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I5320T	Intel 5320T 2.3GHz/150W 20C/30MB DDR4 2933MHz	UCS-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
HCI-CPU-I8362	Intel 8362 2.8GHz/265W 32C/48MB DDR4 3200MHz	HCI-CPU-I8562Y+	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I5315Y=	Intel 5315Y 3.2GHz/140W 8C/12MB DDR4 2933MHz	UCS-CPU-I5515+=	Intel I5515+ 3.2GHz/165W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I6338=	Intel 6338 2.0GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6538Y+=	Intel I6538Y+ 2.2GHz/225W 32C/60MB DDR5 5200MT/s	-
HCI-CPU-I4314	Intel 4314 2.4GHz/135W 16C/24MB DDR4 2667MHz	HCI-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I6334C=	DSITI: Intel 6334 3.6GHz/165W 8C/18MB DDR4 3200MHz	UCS-CPU-I6534C=	DISTI: Intel I6534 3.9GHz/195W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I8360Y	Intel 8360Y 2.4GHz/250W 36C/54MB DDR4 3200MHz	UCS-CPU-I8568Y+	Intel I8568Y+ 2.3GHz/350W 48C/300MB DDR5 5600MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I8360Y=	Intel 8360Y 2.4GHz/250W 36C/54MB DDR4 3200MHz	UCS-CPU-I8568Y+=	Intel I8568Y+ 2.3GHz/350W 48C/300MB DDR5 5600MT/s	-
UCS-CPU-I4309Y	Intel 4309Y 2.8GHz/105W 8C/12MB DDR4 2667MHz	UCS-CPU-I4509Y	Intel I4509Y 2.6GHz/125W 8C/22.5MB DDR5 4400MT/s	-
UCS-CPU-I5320C=	DISTI: Intel 5320 2.2GHz/185W 26C/39MB DDR4 2933MHz	UCS-CPU-I5520+C=	DISTI: Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I4309YC=	DSITI: Intel 4309Y 2.8GHz/105W 8C/12MB DDR4 2667MHz	UCS-CPU-I4509YC=	DISTI: Intel I4509Y 2.6GHz/125W 8C/22.5MB DDR5 4400MT/s	-
HCI-CPU-I4310T	Intel 4310T 2.3GHz/105W 10C/15MB DDR4 2667MHz	HCI-CPU-I4510T	Intel I4510T 2.0GHz/115W 12C/30MB DDR5 4400MT/s	-
UCS-CPU-I4316	Intel 4316 2.3GHz/150W 20C/30MB DDR4 2667MHz	UCS-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
HCI-CPU-I6338N	Intel 6338N 2.2GHz/185W 32C/48MB DDR4 2667MHz	HCI-CPU-I6538N	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I6334	Intel 6334 3.6GHz/165W 8C/18MB DDR4 3200MHz	UCS-CPU-I6534	Intel I6534 3.9GHz/195W 8C/22.5MB DDR5 4800MT/s	-
HCI-CPU-I5317	Intel 5317 3.0GHz/150W 12C/18MB DDR4 2933MHz	HCI-CPU-I6526Y	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
HCI-CPU-I5318Y	Intel 5318Y 2.1GHz/165W 24C/36MB DDR4 2933MHz	HCI-CPU-I6542Y	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I6326C=	DSITI: Intel 6326 2.9GHz/185W 16C/24MB DDR4 3200MHz	UCS-CPU-I6526YC=	DISTI: Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I5315YC=	DSITI: Intel 5315Y 3.2GHz/140W 8C/12MB DDR4 2933MHz	UCS-CPU-I5515+C=	DISTI: Intel I5515+ 3.2GHz/165W 8C/22.5MB DDR5 4800MT/s	-
UCS-CPU-I6330C=	DSITI: Intel 6330 2.0GHz/205W 28C/42MB DDR4 2933MHz	UCS-CPU-I6530C=	DISTI: Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
HCI-CPU-I6342	Intel 6342 2.8GHz/230W 24C/36MB DDR4 3200MHz	HCI-CPU-I6542Y	Intel I6542Y 2.9GHz/250W 24C/60MB DDR5 5200MT/s	-
UCS-CPU-I8358	Intel 8358 2.6GHz/250W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+	Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
HCI-CPU-I6312U	Intel 6312U 2.4GHz/185W 24C/36MB DDR4 3200MHz	HCI-CPU-I5512U	Intel I5512U 2.1GHz/185W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6348=	Intel 6348 2.6GHz/235W 28C/42MB DDR4 3200MHz	UCS-CPU-I6548Y+=	Intel I6548Y+ 2.5GHz/250W 32C/60MB DDR5 5200MT/s	-
UCS-CPU-I4310T	Intel 4310T 2.3GHz/105W 10C/15MB DDR4 2667MHz	UCS-CPU-I4510T	Intel I4510T 2.0GHz/115W 12C/30MB DDR5 4400MT/s	-
HCI-CPU-I8360Y	Intel 8360Y 2.4GHz/250W 36C/54MB DDR4 3200MHz	HCI-CPU-I8568Y+	Intel I8568Y+ 2.3GHz/350W 48C/300MB DDR5 5600MT/s	-
UCS-CPU-I6336YC=	DISTI: Intel 6336Y 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I6554SC=	DISTI: Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I8358C=	DISTI: Intel 8358 2.6GHz/250W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+C=	DISTI: Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I6330N	Intel 6330N 2.2GHz/165W 28C/42MB DDR4 2667MHz	UCS-CPU-I6538N	Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
UCS-CPU-I6312UC=	DISTl: Intel 6312U 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I5512UC=	DISTl: Intel I5512U 2.1GHz/185W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6314UC=	DSITl: Intel 6314U 2.3GHz/205W 32C/48MB DDR4 3200MHz	UCS-CPU-I6530C=	DISTl: Intel I6530 2.1GHz/270W 32C/160MB DDR5 4800MT/s	-
UCS-CPU-I8362C=	DISTl: Intel 8362 2.8GHz/265W 32C/48MB DDR4 3200MHz	UCS-CPU-I8562Y+C=	DISTl: Intel I8562Y+ 2.8GHz/300W 32C/60MB DDR5 5600MT/s	-
UCS-CPU-I4314	Intel 4314 2.4GHz/135W 16C/24MB DDR4 2667MHz	UCS-CPU-I4516Y+	Intel I4516Y+ 2.2GHz/185W 24C/45MB DDR5 4400MT/s	-
UCS-CPU-I6338TC=	DISTl: Intel 6338T 2.1GHz/165W 24C/36MB DDR4 3200MHz	UCS-CPU-I5520+C=	DISTl: Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
UCS-CPU-I6330NC=	DSITl: Intel 6330N 2.2GHz/165W 28C/42MB DDR4 2667MHz	UCS-CPU-I6538NC=	DISTl: Intel I6538N 2.1GHz/205W 32C/60MB DDR5 5200MT/s	-
HCI-CPU-I5320	Intel 5320 2.2GHz/185W 26C/39MB DDR4 2933MHz	HCI-CPU-I5520+	Intel I5520+ 2.2GHz/205W 28C/52.5MB DDR5 4800MT/s	-
HCI-CPU-I8351N	Intel 8351N 2.4GHz/225W 36C/54MB DDR4 2933MHz	HCI-CPU-I6554S	Intel I6554S 2.2GHz/270W 36C/180MB DDR5 5200MT/s	-
UCS-CPU-I5317=	Intel 5317 3.0GHz/150W 12C/18MB DDR4 2933MHz	UCS-CPU-I6526Y=	Intel I6526Y 2.8GHz/195W 16C/37.5MB DDR5 5200MT/s	-
UCS-CPU-I6312U	Intel 6312U 2.4GHz/185W 24C/36MB DDR4 3200MHz	UCS-CPU-I5512U	Intel I5512U 2.1GHz/185W 28C/52.5MB DDR5 4800MT/s	-

Product migration options

The SKUs provided as 'Replacement Product Part Number' are migration SKUs and not meant for replacement as they are not available on the same parent platform server.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

<https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html>.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to:

<https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)