

End-of-Sale and End-of-Life Announcement for the Cisco UCS C885A M8 Rack Servers with NVIDIA HGX H200 GPUs

Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	6
For more information	7

Overview

EOL15913

Cisco announces the end-of-sale and end-of-life dates for the Cisco UCS C885A M8 Rack Servers with NVIDIA HGX H200 GPUs. The last day to order the affected product(s) is June 25, 2026. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Table 1. End-of-life milestones and dates for the Cisco UCS C885A M8 Rack Servers with NVIDIA HGX H200 GPUs

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	May 25, 2026
End-of-Sale Date: HW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 25, 2026
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 23, 2026
End of SW Maintenance Releases Date: HW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 25, 2027
End of Vulnerability/Security Support: HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	June 24, 2029
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	June 25, 2027
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 25, 2027
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	September 20, 2028
Last Date of Support: HW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 30, 2029

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Product part numbers

Table 2. Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description
C885A-M8-CC-SLD02=	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 NG
C885A-M8-CC-SLD21	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 Pollara CX-7
C885A-M8-CC-SLD24	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400DDR5 Pollara, CX-7
C885A-M8-CC-SLD16=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD18	UCS C885A M8 CPU SLED AMD 9575F 96GB DDR5 CX-7s
C885A-M8-CC-SLD16	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD10	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 B3140H B3240
UCSC-885A-M8-M3X1	UCS C885A M8 Rack - MI300X GPU, 8x CX-7, 1x B3220, 2.3TB Mem
C885A-M8-CC-SLD21=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 Pollara CX-7
C885A-M8-DCSCM1=	UCS C885A M8 DC-SCM Card AMD GPU, 5th Gen AMD EPYC CPU HAI
UCSC-885A-M8-M3X6	UCS C885A M8 Rack - MI300X GPU, 8x CX-7, 4x CX-7, 2.3TB Mem
C885A-M8-CC-SLD03=	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD07	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD17=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-MI35-SLD	UCS C885A M8 GPU SLED MI350X
C885A-M8-MI3X-SLD=	UCS C885A M8 GPU SLED MI300X AMD 100-300000069H
C885A-M8-CC-SLD19=	UCS C885A M8 CPU SLED AMD 9575F 96GB 8x B3140H, 1x B3220
UCSC-885A-M8-H27	UCS C885A M8 Rack - H200 GPU, 8x CX-7, 2x B3220, 3TB Mem
UCSC-885A-M8-M3X2	UCS C885A M8 Rack-MI300X GPU, 8x B3140H, 1x B3220, 2.3TB Mem
C885A-M8-CC-SLD01=	UCS C885A M8 CPU SLED AMD 9554 96GB 5600 DDR5 CX-7 B3220
C885A-M8-CC-SLD05	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 AG
C885A-M8-CC-SLD06=	UCS C885A M8 CPU SLED AMD 9535F 64GB 6400 DDR5 CX-7
C885A-M8-DCSCM	UCS C885A M8 DC-SCM Card Nvidia GPU, 5th Gen AMD EPYC CPU
C885A-M8-CC-SLD08=	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD11	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 MB
C885A-M8-CC-SLD15	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD17	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-H2SX-SLD	UCS C885A M8 GPU SLED H200 NV 935-24287-0040-000
UCSC-885A-M8-M3X0	UCS C885A M8 Rack - MI300X GPU, 2x CX-7, 1.5TB Mem
C885A-M8-CC-SLD23=	UCS C885A M8 Rack - H200 GPU, 4x CX-7, 2.3TB Mem
C885A-M8-H2SX-SLD=	UCS C885A M8 GPU SLED H200 NV 935-24287-0040-000
C885A-M8-CC-SLD06	UCS C885A M8 CPU SLED AMD 9535F 64GB 6400 DDR5 CX-7
C885A-M8-CC-SLD18=	UCS C885A M8 CPU SLED AMD 9575F 96GB DDR5 CX-7s

End-of-Sale Product Part Number	Product Description
C885A-M8-CC-SLD20=	UCS C885A M8 CPU SLED AMD 9535 96GB DDR5 2xCX-7s
C885A-M8-DCSCM=	UCS C885A M8 DC-SCM Card Nvidia GPU, 5th Gen AMD EPYC CPU
UCSC-885A-M8-H23	UCS C885A M8 Rack - H200 GPU, 8x CX-7, 2x CX-7, 2.3TB Mem
UCSC-885A-M8-M3X4	UCS C885A M8 Rack - MI300X GPU, 10x CX-7, 3TB Mem
C885A-M8-DCSCM1	UCS C885A M8 DC-SCM Card AMD GPU, 5th Gen AMD EPYC CPU HAI
C885A-M8-H2SXSLD=	UCS C885A M8 GPU SLED H200 NV 935-24287-0040-000
C885A-M8-MI3X-SLD	UCS C885A M8 GPU SLED MI300X AMD 100-300000069H
C885A-M8-CC-SLD07=	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7s
UCSC-885A-M8-H26	UCS C885A M8 Rack - H200 GPU, 8x CX-7, 2x B3220, 2.3TB Mem
C885A-M8-CC-SLD15=	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD01	UCS C885A M8 CPU SLED AMD 9554 96GB 5600 DDR5 CX-7 B3220
UCSC-885A-M8-H20	UCS C885A M8 Rack - H200 GPU, 2x CX-7, 1.5TB Mem
UCSC-885A-M8-H29	UCS C885A M8 Rack - H200 GPU, 12x 400GbE CX-7, 3TB Mem
UCSC-885A-M8-H24	UCS C885A M8 Rack - H200 GPU, 8x 3140, 1x 3220 2.3TB Mem
UCSC-885A-M8-H28	UCS C885A M8 Rack - H200 GPU, 8x B3140H, 2x B3220, 2.3TB Mem
C885A-M8-CC-SLD03	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD09=	UCS C885A M8 CPU SLED AMD 9554 64GB 5600 DDR5 CX-7s
C885A-M8-CC-SLD14	UCS C885A M8 CPU SLED AMD 9535F 64GB 6400 DDR5 CX-7
C885A-M8-CC-SLD02	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 NG
C885A-M8-CC-SLD22=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7
UCSC-885A-M8-M3X3	UCS C885A M8 Rack - MI300X GPU, 8x CX-7, 2x CX-7, 2.3TB Mem
C885A-M8-CC-SLD12=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD22	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7
C885A-M8-H2SXSLD	UCS C885A M8 GPU SLED H200 NV 935-24287-0040-000
UCSC-885A-M8-H25	UCS C885A M8 Rack - H200 GPU, 8x CX-7, 2x CX-7, 3TB Mem
UCSC-885A-M8-M3X5	UCS C885A M8 Rack - MI300X GPU, 8x CX-7, 2x B3220, 2.3TB Mem
C885A-M8-CC-SLD19	UCS C885A M8 CPU SLED AMD 9575F 96GB 8x B3140H, 1x B3220
C885A-M8-CC-SLD08	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7 B3220
C885A-M8-CC-SLD10=	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 B3140H B3240
C885A-M8-CC-SLD11=	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 MB
UCSC-885A-M8-H22	UCS C885A M8 Rack - H200 GPU, 8x B3140H, 1x B3220, 2.3TB Mem

End-of-Sale Product Part Number	Product Description
C885A-M8-CC-SLD12	UCS C885A M8 CPU SLED AMD 9575F 128GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD13=	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD23	UCS C885A M8 Rack - H200 GPU, 4x CX-7, 2.3TB Mem
C885A-M8-CC-SLD09	UCS C885A M8 CPU SLED AMD 9554 64GB 5600 DDR5 CX-7s
UCSC-885A-M8-H21	UCS C885A M8 Rack - H200 GPU, 8x CX-7, 1x B3220, 2.3TB Mem
C885A-M8-CC-SLD05=	UCS C885A M8 CPU SLED AMD9575F 96GB 6400DDR5 B3140H B3220 AG
C885A-M8-CC-SLD13	UCS C885A M8 CPU SLED AMD 9575F 96GB 6400 DDR5 CX-7s
C885A-M8-CC-SLD14=	UCS C885A M8 CPU SLED AMD 9535F 64GB 6400 DDR5 CX-7
UCSC-885A-M8-HC1	UCS C885A M8 Rack - H200 GPU, 8x B3140H, 2x B3240, 3TB Mem

Product migration options

There is no replacement available for the Cisco UCS C885A M8 Rack Servers with NVIDIA HGX H200 GPUs at this time.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at

https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco UCS C885A M8 Rack Servers with NVIDIA HGX H200 GPUs through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to:

<https://www.cisco.com/c/en/us/products/remanufactured.html>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

<https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html>.

For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)