



END-OF-LIFE NOTICE NO. 2207

## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO CATALYST CAMPUS SWITCH ROUTER

Cisco Systems® announces the End-of-Life of the Cisco® Catalyst® Campus Switch Router (CSR) and select multiservice switch router (MSR) line cards. The last day to order the Cisco Catalyst CSR is December 15, 2003. Customers will continue to receive support from the Cisco Technical Assistance Center (TAC) until December 15, 2008. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco Catalyst CSR. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco Catalyst 8500 MSR for ATM and multiservice applications and to the Cisco Catalyst 6500 Series Switch for Layer 2 and Layer 3 switching applications. Information about the Cisco Catalyst 8500 MSR is available at:

<http://www.cisco.com/en/US/products/hw/switches/ps718/index.html>.

Information about the Cisco Catalyst 6500 Series is available at: <http://www.cisco.com/en/US/products/hw/switches/ps708/index.html>.

Table 3 provides relevant information for migrating from the Cisco Catalyst CSR to the Catalyst 8500 MSR or Catalyst 6500 Series.

**Table 1.** End-of-Life Milestones and Dates for the Cisco Catalyst CSR

Milestone	Definition	Date
<b>End-of-life announcement date</b>	The date the document that announces the End-of-Sale and End-of-Life of a product is distributed to the general public.	June 15, 2003
<b>End-of-sale date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 15, 2003
<b>Last shipment date</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	March 15, 2004
<b>End of software maintenance releases date</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	December 15, 2004
<b>End of Routine failure analysis date</b>	The last possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	December 15, 2004
<b>End of new service attachment date</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	December 15, 2004
<b>End of service contract renewal date</b>	The last date to extend or renew a service contract for the product. The extension or renewal period cannot extend beyond the last date of support.	September 15, 2008
<b>Last date of support</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	December 15, 2008

**Table 2.** Product Part Numbers Affected by this Announcement

End-of-Sale Product Part Number	Product Description
C8510CSR-SKIT-AC	C8510CSR starter kit with AC power
C8510CSR-SKIT-DC	Catalyst 8510 CSR starter kit with DC power
C8510-SRP	C8510 CSR Switch Route Processor
C8510-SRP=	C8510 CSR Switch Route Processor (spare)
C8540CSR-SKIT-AC	Catalyst 8540 CSR starter kit with AC power
C8540CSR-SKIT-DC	Catalyst 8540 CSR starter kit with DC power
C8541CSR-RP	Catalyst 8540 CSR Route Processor - installed
C8541CSR-RP=	Catalyst 8540 CSR Route Processor (spare)
C8541CSR-RP/2	Catalyst 8540 CSR Redundant Route Processor - installed
C8542CSR-SP	Catalyst 8540 CSR Switch Processor - installed
C8542CSR-SP=	Catalyst 8540 CSR Switch Processor (spare)
C8542CSR-SP/2	Catalyst 8540 CSR Redundant Switch Processor
L1010-ATM-EU	LightStream® 1010 ATM switch promotional bundle
C85FE-8F-64K	C8510 8-port 100-FX MT-RJ 64K
C85FE-8F-64K=	C8510 8-port 100-FX MT-RJ 64K (spare)
C85FE-16FACL-64K	C8540 16-port 100-FX MT-RJ with ACL 64K
C85FE-16FACL-64K =	C8540 16-port 100-FX MT-RJ with ACL 64K (spare)
C85MS-1F4S-OC48SS	C8540 1-port OC-48c SMF-IR + 4 x OC-12 SMF-IR
C85MS-1F4S-OC48SS=	C8540 1-port OC-48c SMF-IR + 4 x OC-12 SMF-IR (spare)
C85MS-1F4M-OC48SS	C8540 1-port OC-48c SMF-IR + 4 x OC-12 MMF
C85MS-1F4M-OC48SS=	C8540 1-port OC-48c SMF-IR + 4 x OC-12 MMF (spare)
C85EGE-2X-16K	C8540 2-port enhanced gigabit Ethernet 16K
C85EGE-2X-16K=	C8540 2-port enhanced gigabit Ethernet 16K (spare)

## PRODUCT MIGRATION OPTIONS

The recommended replacements for the Cisco Catalyst CSR are the Cisco Catalyst 8500 MSR and the Catalyst 6500 Series (Table 3).

**Table 3.** Product Comparisons

	Cisco Catalyst CSR	Replacement Product
Feature	ATM, multiservice	Cisco Catalyst 8500 MSR
Feature	Layer 2, Layer 3 switching	Cisco Catalyst 6500 Series

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>.

**Note:** The Cisco TMP application requires all users to have a Cisco.com user ID.



## **ADDITIONAL INFORMATION**

For more information about Cisco products, please contact your Cisco account manager and/or Cisco Channel Partner.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive End-of-Life/End-of-Sale information please go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica  
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR  
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico  
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia  
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

