

## End-of-Sale and End-of-Life Announcement for the Cisco MGX 8950 ATM Multiservice Switch and Software

EOL7161

Cisco announces the end-of-sale and end-of life dates for the Cisco MGX 8950 ATM Multiservice Switch and Software. The last day to order the affected product(s) is July 30, 2011. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco MGX 8950 ATM Multiservice Switch and Software

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	July 30, 2010
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	July 30, 2011
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 28, 2011
<b>Last Ship Date: OS SW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	October 29, 2011
<b>End of SW Maintenance Releases Date: OS SW, HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	July 29, 2014
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	July 29, 2012
<b>End of New Service Attachment Date: OS SW, HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	July 29, 2012
<b>End of Service Contract Renewal Date: OS SW, HW</b>	The last date to extend or renew a service contract for the product.	October 28, 2015
<b>Last Date of Support: HW</b>	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	July 31, 2016

HW = Hardware      OS SW = Operating System Software      App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
DOUBLE-BC-CVR	Full-height Back Card Slot Cover	See the Product Migration Options section below for detailed information on replacing this product.		
DOUBLE-BC-CVR=	Full-height Back Card Slot Cover	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
MGX-8950-AC-R	MGX 8950, 12 I/O, 4 XM-60, 2 AC Tray, 4 PSU, Power Cables	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-8950-DOOR	MGX 8950 door	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-8950-DOOR=	MGX 8950 door	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-APS-CON-8950	APS connector for MGX 8950	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-APS-CON-8950=	APS connector for MGX 8950	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-MNT23-8950	Mounting Kit to install Cisco MGX 8950 in a 23-in rack	See the Product Migration Options section below for detailed information on replacing this product.		
MGX-MNT23-8950=	Mounting Kit to install Cisco MGX 8950 in a 23-in rack	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950	MGX8950 12 I/O slots 4XM60s, Fans, Plenum	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-CAB-MGMT	MGX 8950 Cable Management	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-CAB-MGMT=	MGX 8950 Cable Management	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-EXTDR-CON	AXSM-XG Extender Connector for MGX 8950	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-EXTDR-CON=	AXSM-XG Extender Connector for MGX 8950	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-SW-5210	MGX 8950 Syst Software License- Release (Version 5.2.10)	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-SW-5320	MGX 8950 Syst Software License - Release (Version 5.3.20)	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-SW-5400	MGX 8950 Syst Software License- Release (Version 5.4.00)	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-SW-5430	MGX 8950 Syst Software License- Release (Version 5.4.30)	See the Product Migration Options section below for detailed information on replacing this product.		

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
MGX8950-SW-5500	MGX 8950 Syst Software License- Release (Version 5.5.00)	See the Product Migration Options section below for detailed information on replacing this product.		
MGX8950-SW-5510	MGX 8950 Syst Software License- Release (Version 5.5.10)	See the Product Migration Options section below for detailed information on replacing this product.		
PWRCD-30A-NA	MGX 30A AC Power Input Cord North America	See the Product Migration Options section below for detailed information on replacing this product.		
PWRCD-30A-NA-RA	MGX 30A AC Power Input Cord North America, Right-Angled	See the Product Migration Options section below for detailed information on replacing this product.		
PWRCD-30A-NA-RA=	MGX 30A AC Power Input Cord North America, Right-Angled	See the Product Migration Options section below for detailed information on replacing this product.		
PWRCD-30A-NA=	MGX 30A AC Power Input Cord North America	See the Product Migration Options section below for detailed information on replacing this product.		
PROCESSOR CVR	Double height front card slot cover for the MGX Processor	See the Product Migration Options section below for detailed information on replacing this product.		
PROCESSOR CVR=	Double height front card slot cover for the MGX Processor	See the Product Migration Options section below for detailed information on replacing this product.		

Please also refer to the following End-of-Life/End-of-Sale bulletins associated with this announcement.

**Table 3.** Related bulletins info

End-of-Sale Product Part Number	Product Description	Bulletin Details
MGX 8830/B	Cisco MGX 8830/B ATM Multiservice Switch and Software	EOL7110, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
MGX 8850/B	Cisco MGX 8850/B ATM Multiservice Switch and Software	EOL7160, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
MGX 8950	Cisco MGX 8950 ATM Multiservice Switch and Software	EOL7161, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
VISM-PR	Cisco MGX VISM-PR Modules, Back Cards and Software	EOL7163, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
AXSM	Cisco MGX AXSM Modules and Back Cards	EOL7164, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
MPSM	Cisco MGX MPSM Modules and Back Cards	EOL7165, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
RPM-PR	Cisco MGX RPM-PR Modules and Back Cards	EOL7162, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>
SRME/B	Cisco MGX SRME/B Modules and Back Cards	EOL7183, <a href="http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html">http://www.cisco.com/en/US/products/hw/switches/ps1938/prod_eol_notices_list.html</a>

## Product Migration Options

Customers are encouraged to migrate to the Cisco 12000 Series Routers, Cisco Carrier Routing System, or the Cisco 7600 Series Routers. Information about the Cisco 12000 Series can be found at:

<http://www.cisco.com/en/US/products/hw/routers/ps167/>. Information about the CRS can be found at: <http://www.cisco.com/en/US/products/ps5763/index.html>. Information about the Cisco 7600 Series can be found at: <http://www.cisco.com/en/US/products/hw/routers/ps368/index.html>.

Customers can use the Cisco Technology Migration Program (TMP) to trade-in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at <http://www.cisco.com/web/partners/pr11/incentive/tmp/index.html>.

Customers may be able to continue to purchase the Cisco MGX 8950 ATM Multiservice Switch and Software through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco 12000 Series Routers, Cisco Carrier Routing System, or Cisco 7600 Series Routers, visit <http://www.cisco.com/en/US/products/hw/routers/ps167/>; <http://www.cisco.com/en/US/products/ps5763/index.html>; and <http://www.cisco.com/en/US/products/hw/routers/ps368/index.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html)

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application: [http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).



**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV  
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco Logo are trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and other countries. A listing of Cisco's trademarks can be found at [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1005R)