

# End-of-Sale and End-of-Life Announcement for the Cisco Nexus 3048 Switch

---

# Contents

Overview	3
End-of-life milestones	3
Product part numbers	4
Product migration options	4
For more information	6

## Overview

### EOL13329 - Amended

Cisco announces the end-of-sale and end-of life dates for the Cisco Nexus 3048 Switch. The last day to order the affected product(s) is August 3, 2020. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

### End-of-life milestones

**Table 1.** End-of-life milestones and dates for the Cisco Nexus 3048 Switch

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	February 3, 2020
<b>End-of-Sale Date: HW</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 3, 2020
<b>Last Ship Date: HW</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 1, 2020
<b>End of SW Maintenance Releases Date: HW</b>	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	August 3, 2021
<b>End of Vulnerability/Security Support: HW</b>	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	August 3, 2023
<b>End of Routine Failure Analysis Date: HW</b>	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 3, 2021
<b>End of New Service Attachment Date: HW</b>	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 3, 2021
<b>End of Service Contract Renewal Date: HW</b>	The last date to extend or renew a service contract for the product.	October 29, 2024
<b>Last Date of Support: HW</b>	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 31, 2025

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

## Product part numbers

**Table 2.** Product part numbers affected by this announcement

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>C1-N3K-C3048TP</b>	Cisco ONE Nexus 3048TP-1GE 1RU 48x10/100/1K and 4x10GE ports	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-1PS</b>	Nexus 3048TP-1GE 1RU 48 1GE and 4 10GE ports, 1 PSU	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-BA-L3</b>	Nexus 3048, Rev Airflow (port side intake), AC P/S, LAN Ent	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-BD-L3</b>	Nexus 3048, Rev Airflow (port side intake) DC P/S, LAN Ent L	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-FA-L3</b>	Nexus 3048, Std Airflow (port side exhaust), AC P/S, LAN Ent	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-FD-L3</b>	Nexus 3048, Std Airflow (port side exhaust),DC P/S, LAN Ent	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-OE</b>	Nexus 3048 switch, Open Env	There is currently no migration product available for this product.	-	-
<b>N3K-C3048-OE=</b>	Nexus 3048 OE Switch	There is currently no migration product available for this product.	-	-
<b>N3K-C3048-ZF-1BA</b>	Nexus 3048, Reverse airflow, 1PSU, L2 only ZF spl Bundle	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-ZF-1BD</b>	Nexus 3048, Reverse airflow, 1PSU, L2 only ZF spl Bundle	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-ZF-1FA</b>	Nexus 3048, std airflow, 1PSU, L2 only ZF spl Bundle	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-ZF-1FD</b>	Nexus 3048, Std airflow, 1PSU, L2 only ZF spl Bundle	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>N3K-C3048-ZM-B</b>	Nexus 3048 Rev Airflow (port side intake) with L3, ZM Spl Bu	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048-ZM-F</b>	Nexus 3048 Std Airflow (port side exhaust) with L3, ZM Spl B	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048TP-10PK</b>	Nexus 3048TP-E 10PK Bundle	There is currently no migration product available for this product.	-	-
<b>N3K-C3048TP-10PKBN</b>	Nexus 3048TP-1GE 10Pack Bundle PID	There is currently no migration product available for this product.	-	-
<b>N3K-C3048TP-1GE</b>	Nexus 3048TP-1GE 1RU 48 x 10/100/1000 and 4 x 10GE ports	N9K-C92348GC-X	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-C3048TP-1GE++</b>	Nexus 3048TP-1GE 1RU 48 x 10/100/1000 and 4x10GE ports (TAA)	There is currently no migration product available for this product.	-	-
<b>N3K-C3048TP-1GE=</b>	Nexus 3048TP-1GE 1RU 48 1GE and 4 10GE ports, no p/s,no fan	N9K-C92348GC-X=	^Nexus 9200 with 48p 100M/1GT, 4p 10/25G & 2p 40/100G QSFP28	-
<b>N3K-UCS3048-F</b>	Nexus 3048 for UCS Smart Play	There is currently no migration product available for this product.	-	-
<b>N3K-C3048-ZM-1BS</b>	^N3048 Rev AF (port side intake) 2 AC PSU, 1 SFP MM, ZM bun	There is currently no migration product available for this product.	-	-
<b>N3K-C3048-ZM-1FS</b>	^N3048 Fwd AF (port side exhaust) 2 AC PSU, 1 SFP MM, ZM bun	There is currently no migration product available for this product.	-	-
<b>N3K-C3048-ZM-2BS</b>	^N3048 Rev AF (port side intake) 2 AC PSU, 2 SFP MM, ZM bun	There is currently no migration product available for this product.	-	-

End-of-Sale Product Part Number	Product Description	Migration Product Part Number	Migration Product Description	Additional Information
<b>N3K-C3048-ZM-2FS</b>	^N3048 Fwd AF (port side exhaust) 2 AC PSU, 2 SFP MM, ZM bun	There is currently no migration product available for this product.	-	-

## Product migration options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at [https://www.cisco.com/web/partners/incentives\\_and\\_promotions/tmp.html](https://www.cisco.com/web/partners/incentives_and_promotions/tmp.html).

Customers may be able to continue to purchase the Cisco Nexus 3048 Switch through the Cisco Refresh (certified remanufactured) program. Remanufactured units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Refresh program, go to: <https://www.cisco.com/c/en/us/products/remanufactured.html>.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: <https://www.cisco.com/c/en/us/about/takeback-and-reuse/product-recycling.html>.

## For more information

For more information about the Cisco End-of-Life Policy, go to: <https://www.cisco.com/c/en/us/products/eos-eol-policy.html>.

For more information about the Cisco Product Warranties, go to: <https://www.cisco.com/c/en/us/products/warranty-listing.html>.

To subscribe to receive end-of-life/end-of-sale information, go to: <https://cway.cisco.com/mynotifications>.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)