



END-OF-LIFE NOTICE, NO. 2832

END-OF-LIFE ANNOUNCEMENT—V3.3 ASSEMBLIES

TIMELINE

End-of-Sale: May 30, 1998

Last Date of Support: May 30, 2003

Note: The support date listed above applies to hardware support. V3.3 software support was retired May 30, 1998.

REPLACEMENT PRODUCTS

These assemblies have been replaced by the V5.1 series of VCO products.

Assembly Number	Description
VCO/80 Equipment for Release V3.3	
35019050133	Basic System VCO/80 DC
35019050233	Basic System VCO/80 DC—Zone 4 Earthquake Hardened
35019250133	Basic System VCO/80 AC
35019250233	Basic System VCO/80 AC—Zone 4 Earthquake Hardened
61001000033	VCO Documentation Set (with System)
35019150133	Control/Storage/Power Redundancy DC
35019350133	Control/Storage/Power Redundancy AC
Preconfigured VCO/80 Digital System Packages—V3.3	
35022811133	24SPAN VCO80 T1 SYS PKG DC Z2 4.0
35022812133	24SPAN VCO80 T1 SYS PKG DC Z4 4.0
35022821133	24SPAN VCO80 T1 SYS PKG AC Z2 4.0
35022822133	24SPAN VCO80 T1 SYS PKG AC Z4 4.0
35022911133	36SPAN VCO80 T1 SYS PKG DC Z2 4.0
35022912133	36SPAN VCO80 T1 SYS PKG DC Z4 4.0
35022921133	36SPAN VCO80 T1 SYS PKG AC Z2 4.0
35022922133	36SPAN VCO80 T1 SYS PKG AC Z4 4.0
35023011133	48SPAN VCO80 T1 SYS PKG DC Z2 4.0
35023012133	48SPAN VCO80 T1 SYS PKG DC Z4 4.0
35023021133	48SPAN VCO80 T1 SYS PKG AC Z2 4.0
35023022133	48SPAN VCO80 T1 SYS PKG AC Z4 4.0
35023111133	60SPAN VCO80 T1 SYS PKG DC Z2 4.0
35023112133	60SPAN VCO80 T1 SYS PKG DC Z4 4.0
35023121133	60SPAN VCO80 T1 SYS PKG AC Z2 4.0
35023122133	60SPAN VCO80 T1 SYS PKG AC Z4 4.0
35023211233	24SPAN VCO80 75OHM E1 SYS PKG DC Z2 4.0

Cisco Systems, Inc.

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

Assembly Number	Description
35023211333	24SPAN VCO80 120OHM E1 SYS PKG DC Z2 4.0
35023212233	24SPAN VCO80 75OHM EA SYS PKG DC Z4 4.0
35023212333	24SPAN VCO80 120OHM E1 SYS PKG DC Z4 4.0
35023221233	24SPAN VCO80 75OHM E1 SYS PKG AC Z2 4.0
35023221333	24SPAN VCO80 120OHM E1 SYS PKG AC Z2 4.0
35023222233	24SPAN VCO80 75OHM E1 SYS PKG AC Z4 4.0
35023222333	24SPAN VCO80 120OHM E1 SYS PKG AC Z4 4.0
35023311233	36SPAN VCO80 75OHM E1 SYS PKG DC Z2 4.0
35023311333	36SPAN VCO80 120OHM E1 SYS PKG DC Z2 4.0
35023312233	36SPAN VCO80 75OHM E1 SYS PKG DC Z4 4.0
35023312333	36SPAN VCO80 120OHM E1 SYS PKG DC Z4 4.0
35023321233	36SPAN VCO80 75OHM E1 SYS PKG AC Z2 4.0
35023321333	36SPAN VCO80 120OHM E1 SYS PKG AC Z2 4.0
35023322233	36SPAN VCO80 75OHM E1 SYS PKG AC Z4 4.0
35023322333	36SPAN VCO80 120OHM E1 SYS PKG AC Z4 4.0
35023411233	48SPAN VCO80 75OHM E1 SYS PKG DC Z2 4.0
35023411333	48SPAN VCO80 120OHM E1 SYS PKG DC Z2 4.0
35023412233	48SPAN VCO80 75OHM E1 SYS PKG DC Z4 4.0
35023412333	48SPAN VCO80 120OHM E1 SYS PKG DC Z4 4.0
35023421233	48SPAN VCO80 75OHM E1 SYS PKG AC Z2 4.0
35023421333	48SPAN VCO80 120OHM E1 SYS PKG AC Z2 4.0
35023422233	48SPAN VCO80 75OHM E1 SYS PKG AC Z4 4.0
35023422333	48SPAN VCO80 120OHM E1 SYS PKG AC Z4 4.0
VCO/80 V3.3 Specific Spares	
35009650133	System Spares Kit (V3.3)
50148080233	Network Bus Controller (NBC)
20122450133	CPU 8MB (VME 68030 Processor)
Generic Release V3.3 Software	
35014950233	Generic—Initial 696 Time Slots
35011450133	Ethernet Host Link
35008250133	TeleRouter Application Software
35008450133	ISDN Primary Rate Software
35008650133	ISDN NFAS Software
35008550133	NT-DASS-2 ISDN Software
35014350133	DPNSS ISDN Software
35020550133	NET5 ISDN Software
Integrated SS7 Software Options	
35024650100	Integrated. SS7 Basic Software—ANSI ISUP
35025250100	Integrated. SS7 Basic Software—ANSI TCAP Upgrade
35024750100	Integrated. SS7 Redundancy Software—ANSI ISUP

Assembly Number	Description
35025450100	Integrated. SS7 Redundancy Software—ANSI TCAP Upgrade
35024850100	Integrated. SS7 Basic Software—CCITT/HK/THAI ISUP
35025550100	Integrated. SS7 Basic Software—CCITT TCAP Upgrade
35024950100	Integrated. SS7 Redundancy Software—CCITT/HK/THAI ISUP
35025650100	Integrated. SS7 Redundancy Software—CCITT TCAP Upgrade
Host Application Development Software	
35011050133	ASIST API
35011150100	ASIST ADLC

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica
Croatia • Cyprus • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR
Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico
The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia
Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

All contents are Copyright © 1992–2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) VS/LW8343 04/05

