

End-of-Sale and End-of-Life Announcement for the Selected Cisco BTS 10200 Softswitch Components

EOL6625 - Amended

Cisco® announces the end-of-sale and end-of life dates for the Selected Cisco BTS 10200 Softswitch Components. The last day to order the affected product(s) is June 7, 2009. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Selected Cisco BTS 10200 Softswitch Components

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 7, 2008
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 7, 2009
Last Ship Date: App. SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 5, 2009
End of SW Maintenance Releases Date: App. SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 7, 2010
End of New Service Attachment Date: App. SW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 7, 2010
End of Service Contract Renewal Date: App. SW	The last date to extend or renew a service contract for the product.	September 3, 2011
Last Date of Support: App. SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 6, 2012

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
BTS-SW-3.5K9-NO	BTS 10200 R3.5.X software - External Oracle License Required	See the Product Migration Options section below for detailed information on replacing this product.	
BTS-SW-LNP	LNP RTU License for BTS 10200 - Per Platform	See the Product Migration Options section below for detailed information on replacing this product.	
BTS-SW-LNP=	LNP RTU License for BTS 10200 - Per Platform	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-100P	BTS10200 Platform RTU (100 CPS)	See the Product Migration Options section below for detailed information	

		on replacing this product.	
BTS10200-100P=	REF:BTS10200 Platform RTU (100 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-10P	BTS10200 Platform RTU (10 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-10P=	Spares, Additional BTS 10200 CPS	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-25P	BTS10200 Platform RTU (25 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-25P=	Spares, Additional CPS - 25K	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-50P	BTS10200 Platform RTU (50 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-50P=	REF:BTS10200 Platform RTU (50 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-75P	BTS10200 Platform RTU (75 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-75P=	REF:BTS10200 Platform RTU (75 CPS)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-RTU-T10=	Ref: BTS10200 Tandem RTU in bundles of 1K (10K-49K)	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-SW-SPM	BTS 10200 Software License for Multiple Line IP Phone	See the Product Migration Options section below for detailed information on replacing this product.	
BTS10200-SW-SPS	BTS 10200 Software License for Single Line IP Phone	See the Product Migration Options section below for detailed information on replacing this product.	

Product Migration Options

The listed Cisco BTS 10200 Softswitch components have reached their end of life. These parts are now included in the base and RTUs.

Service prices for Cisco products are subject to change after the product End of Sale date.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV
Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0809R)