



End-of-Sale and End-of-Life Announcement for the Cisco IAD880 Series Integrated Access Devices

EOL7624

Cisco announces the end-of-sale and end-of life dates for the Cisco IAD880 Series Integrated Access Devices. The last day to order the affected product(s) is August 7, 2012. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available until the termination date of the contract, even if this date exceeds the Last Date of Support shown in Table 1.

Table 1. End-of-Life Milestones and Dates for the Cisco IAD880 Series Integrated Access Devices

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	February 7, 2012
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	August 7, 2012
Last Ship Date: HW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	November 5, 2012
End of Routine Failure Analysis Date: HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	August 7, 2013
End of New Service Attachment Date: HW	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	August 7, 2013
End of Service Contract Renewal Date: HW	The last date to extend or renew a service contract for the product.	November 2, 2016
Last Date of Support: HW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	August 31, 2017

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
IAD881B-K9	Cisco IAD881 ENet BRI Sec Router	See Product Migration Options section for details.	C881-V-K9	
IAD881BW-GN-A-K9	Cisco IAD881 Enet BRI SEC Router 802.11n FCC Comp	See Product Migration Options section for details.	C881-V-K9 with Cisco Access Point	
IAD881BW-GN-E-K9	Cisco IAD881 ENet BRI Sec Router 802.11n ETSI Comp	See Product Migration Options section for details.	C881-V-K9 with Cisco Access Point	
IAD881F-K9	Cisco IAD881 ENet FXS Sec Router	See Product Migration Options section for details.	C881-V-K9	
IAD881FW-GN-A-K9	Cisco IAD881 ENet FXS Sec Router 802.11n FCC Comp	See Product Migration Options section for details.	C881-V-K9 with Cisco Access Point	
IAD881FW-GN-E-K9	Cisco IAD881 ENet FXS Sec Router 802.11n ETSI Comp	See Product Migration Options section for details.	C881-V-K9 with Cisco Access Point	
IAD886B-K9	Cisco IAD886 ADSL2+ Annex B Sec BRI Sec Router w/ ISDN B/U	There is currently no replacement product available for this product.		
IAD886BW-GN-E-K9	Cisco IAD886 ADSL2+ AnxB BRI Sec ISDN B/U 802.11n ETSI Comp	There is currently no replacement product available for this product.		
IAD886F-K9	Cisco IAD886 ADSL2 Annex B Sec FXS Sec Router w/ ISDN B/U	There is currently no replacement product available for this product.		
IAD886FW-GN-E-K9	Cisco IAD886 ADSL2+ AnxB FXS Sec ISDN B/U 802.11n ETSI Comp	There is currently no replacement product available for this product.		
IAD887B-K9	Cisco IAD887 ADSL2+ Annex A / BRI / Sec Router w/ ISDN B/U	See Product Migration Options section for details.	C887VA-V-K9	
IAD887BW-GN-A-K9	Cisco IAD887 ADSL2+ AnxA BRI Sec ISDN B/U 802.11n FCC Comp	See Product Migration Options section for details.	C887VA-V-K9 with Cisco Access Point	
IAD887BW-GN-E-K9	Cisco IAD887 ADSL2+ AnxA BRI Sec ISDN B/U 802.11n ETSI Comp	See Product Migration Options section for details.	C887VA-V-W-E-K9	
IAD887F-K9	Cisco IAD887 ADSL2+ AnxA / FXS / Sec Router w/ ISDN B/U	See Product Migration Options section for details.	C887VA-V-K9	
IAD887FW-GN-A-K9	Cisco IAD887 ADSL2+ AnxA FXS Sec ISDN B/U 802.11n FCC Comp	See Product Migration Options section for details.	C887VA-V-K9 with Cisco Access Point	
IAD887FW-GN-E-K9	Cisco IAD887 ADSL2+ AnxA FXS Sec ISDN B/U 802.11n ETSI Comp	See Product Migration Options section for details.	C887VA-V-W-E-K9	

Product Migration Options

Customers are encouraged to migrate to the Cisco 880 Integrated Services Routers. Information about this product can be found at:

http://www.cisco.com/en/US/prod/collateral/routers/ps380/data_sheet_c78_459542_ps380_Products_Data_Sheet.html

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html

Customers may be able to continue to purchase the Cisco IAD880 Series Integrated Access Devices through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html

For More Information

For more information about the Cisco 880 Integrated Services Routers, visit

http://www.cisco.com/en/US/prod/collateral/routers/ps380/data_sheet_c78_459542_ps380_Products_Data_Sheet.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA

C51-699389-00 02/12

© 2012 Cisco and/or its affiliates. All rights reserved. This document is Cisco Public.

Page 4 of 4