



## End-of-Sale and End-of-Life Announcement for the Cisco DCM Series D9900/D9901 AVC/MPEG-2 HD-to-SD Digital Content Licenses

EOL9335

Cisco announces the end-of-sale and end-of-life dates for the Cisco DCM Series D9900/D9901 AVC/MPEG-2 HD-to-SD Digital Content Licenses. The last day to order the affected product(s) is April 14, 2014. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions, even if this date exceeds the Last Date of Support shown in Table 1.

**Table 1.** End-of-Life Milestones and Dates for the Cisco DCM Series D9900/D9901 AVC/MPEG-2 HD-to-SD Digital Content Licenses

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	October 14, 2013
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 14, 2014
<b>Last Ship Date License</b>	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 13, 2014

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
BDCM-HD2SD-DOWNC	D9900/D9901 BU AVC/MPEG-2 HD to SD DC Lic (1/prg; req MFP)	BDCM-AVCSD2HDU	D9900/D9901 BU AVC SD to HD TR/TC Upgr Lic (1/prg; req MFP)	-
BDCM-HD2SD-DOWNC	D9900/D9901 BU AVC/MPEG-2 HD to SD DC Lic (1/prg; req MFP)	BDCM-MP2SD2HDU	D9900/D9901 BU MPEG-2 SD to HD TR/TC Upgr Lic (1/prg;req MFP)	-
LDCM-HD2SD-DOWNC	D9900/D9901 AVC/MPEG-2 HD to SD DC Lic (1/prg; req MFP)	LDCM-AVCSD2HDU	D9900/D9901 AVC SD to HD TR/TC Upgr Lic (1/prg; req MFP)	-
LDCM-HD2SD-DOWNC	D9900/D9901 AVC/MPEG-2 HD to SD DC Lic (1/prg; req MFP)	LDCM-MP2SD2HDU	D9900/D9901 MPEG-2 SD to HD TR/TC Upgr Lic (1/prg; req MFP)	-

---

## Product Migration Options

Customers are encouraged to migrate to the codec-specific versions. Information about this product can be found at: <http://www.cisco.com/en/US/products/ps9230/index.html>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses dispose properly of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

[http://www.cisco.com/web/about/ac227/ac228/ac231/about\\_cisco\\_takeback\\_recycling.html](http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html).

## For More Information

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html).

\*\* For more information about the Cisco Product Warranties, go to:

[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html).

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

## Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml).

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




---

Americas Headquarters  
Cisco Systems, Inc.  
San Jose, CA

Asia Pacific Headquarters  
Cisco Systems (USA) Pte. Ltd.  
Singapore

Europe Headquarters  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)