

End-of-Sale and End-of-Life Announcement for the Cisco DCM series Licenses

EOL11638

Cisco announces the end-of-sale and end-of-life dates for the Cisco DCM series Licenses. The last day to order the affected product(s) is September 8, 2017. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

Table 1. End-of-Life Milestones and Dates for the Cisco DCM series Licenses

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public.	March 10, 2017
End-of-Sale Date License	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	September 8, 2017
Last Ship Date License	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	December 7, 2017

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
BDCM-AVCHDEN-PQ	D9902 BU AVC HD Premium Encode Lic (1/prg; req MFP MK2)	BDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-AVCHDTC	D9900/D9901 BU AVC HD Transcoding Lic (1/prg; req MFP)	BDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-AVCHDTC-PQ	D9900/01/02 BU AVC HD Premium TC Lic (1/prg; req MFP)	BDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-AVCSDEN-PQ	D9902 BU AVC SD Premium Encode Lic (1/prg; req MFP MK2)	BDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-AVCSBTC	D9900/D9901 BU AVC SD Transcoding Lic (1/prg; req MFP)	BDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-AVCSBTC-PQ	D9900/01/02 BU AVC SD Premium TC Lic (1/prg; req MFP)	BDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-COP3-500	D9900/D9901 BU COP3 FEC Lic for up to 500 TS (req. FEC Card)	BDCM-COP3-50	D9900/D9901 BU COP3 FEC Lic for up to 50 TS (req. FEC Card)	-
BDCM-MP2HDEN-PQ	D9902 BU MPEG-2 HD Premium Encode Lic (1/prg; req MFP MK2)	BDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
BDCM-MP2HDTC	D9900/D9901 BU MPEG-2 HD Transcoding Lic (1/prg; req MFP)	BDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-MP2HDTC-PQ	D9900/01/02 BU MPEG-2 HD Premium TC Lic (1/prg; req MFP)	BDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-MP2SDEN-PQ	D9902 BU MPEG-2 SD Premium Encode Lic (1/prg; req MFP MK2)	BDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-MP2SDTC	D9900/D9901 BU MPEG-2 SD Transcoding Lic (1/prg; req MFP)	BDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
BDCM-MP2SDTC-PQ	D9900/01/02 BU MPEG-2 SD Premium TC Lic (1/prg; req MFP)	BDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC BU Lic (1/prg; req MFP)	-
LDCM-AVCHDEN-PQ	D9902 AVC HD Premium Encode Lic (1/prg; req MFP MK2)	LDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-AVCHDTC	D9900/D9901 AVC HD Transcoding Lic (1/prg; req MFP)	LDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-AVCHDTC-PQ	D9900/01/02 AVC HD Premium TC Lic (1/prg; req MFP)	LDCM-AVCHDPQHID-XC	D9900/01/02 AVC HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-AVCSDEN-PQ	D9902 AVC SD Premium Encode Lic (1/prg; req MFP MK2)	LDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-AVCSDTC	D9900/D9901 AVC SD Transcoding Lic (1/prg; req MFP)	LDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-AVCSDTC-PQ	D9900/01/02 AVC SD Premium TC Lic (1/prg; req MFP)	LDCM-AVCSDPQHID-XC	D9900/01/02 AVC SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2HDTC	D9900/D9901 MPEG-2 HD Transcoding Lic (1/prg; req MFP)	LDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2HDTC-PQ	D9900/01/02 MPEG-2 HD Premium TC Lic (1/prg; req MFP)	LDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2SDEN-PQ	D9902 MPEG-2 SD Premium Encode Lic (1/prg; req MFP MK2)	LDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2SDTC	D9900/D9901 MPEG-2 SD Transcoding Lic (1/prg; req MFP)	LDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2SDTC-PQ	D9900/01/02 MPEG-2 SD Premium TC Lic (1/prg; req MFP)	LDCM-MP2SDPQHID-XC	D9900/01/02 MPEG-2 SD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-MP2HDEN-PQ	D9902 MPEG-2 HD Premium Encode Lic (1/prg; req MFP MK2)	LDCM-MP2HDPQHID-XC	D9900/01/02 MP2 HD PPQ/HiD TC/ENC Lic (1/prg; req MFP)	-
LDCM-COP3-500	D9900/D9901 COP3 FEC Lic for up to 500 TS (req. FEC Card)	LDCM-COP3-50	D9900/D9901 COP3 FEC Lic for up to 50 TS (req. FEC Card)	-

Product Migration Options

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)