



End-of-Sale and End-of-Life Announcement for the Cisco XFP QAM Transmitters

EOL11379

Cisco announces the end-of-sale and end-of-life dates for the Cisco XFP QAM Transmitters. The last day to order the affected product(s) is July 6, 2017. Customers with active service contracts or active warranties will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active service contracts or active product warranties, support will be available for the shown dates as stated in the applicable service contracts or product warranty terms and conditions.

Table 1. End-of-Life Milestones and Dates for the Cisco XFP QAM Transmitters

| Milestone | Definition | Date |
|---|---|-----------------|
| End-of-Life Announcement Date | The date the document that announces the end-of-sale and end-of-life of a product is distributed to the general public. | January 5, 2017 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | July 6, 2017 |
| Last Ship Date: HW | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | October 4, 2017 |
| End of Routine Failure Analysis Date: HW | The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect. | July 6, 2018 |
| End of New Service Attachment Date: HW | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | July 6, 2018 |
| End of Service Contract Renewal Date: HW | The last date to extend or renew a service contract for the product. | October 1, 2021 |
| Last Date of Support: HW | The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete. Warranty duration is based on product ship dates; refer to warranty terms and conditions for details. | July 31, 2022 |

HW = Hardware OS SW = Operating System Software App. SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| 1RU-DRF-XFP= | 1RU Chassis for 12 XFP Tx; NC and BC port;CCB3 Control | There is currently no replacement product available for this product. | - | - |
| P2-HM-XFP= | XD Host Module for XFP-RF Transmitter | There is currently no replacement product available for this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| P2-XDP-1RU-ACPS= | Replaceable AC Power Supply for XFP 1RU Chassis | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| P2-XDP-1RU-DCPS= | Replaceable DC Power Supply for XFP 1RU Chassis | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| P2-XDP-1RU-XFP10= | 1RU Chassis for 10 XFP Tx; single input port; SNMP control | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU20= | XFP-RF QAM Transmitter APC ITU 20 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU23= | XFP-RF QAM Transmitter APC ITU 23 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU25= | XFP-RF QAM Transmitter APC ITU 25 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU27= | XFP-RF QAM Transmitter APC ITU 27 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU29= | XFP-RF QAM Transmitter APC ITU 29 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU30= | XFP-RF QAM Transmitter APC ITU 30 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU31= | XFP-RF QAM Transmitter APC ITU 31 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU32= | XFP-RF QAM Transmitter APC ITU 32 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU34= | XFP-RF QAM Transmitter APC ITU 34 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU35= | XFP-RF QAM Transmitter APC ITU 35 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU37= | XFP-RF QAM Transmitter APC ITU 37 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU38= | XFP-RF QAM Transmitter APC ITU 38 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU40= | XFP-RF QAM Transmitter APC ITU 40 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| XFP-RF-ITU41= | XFP-RF QAM Transmitter APC ITU 41 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU42= | XFP-RF QAM Transmitter APC ITU 42 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU43= | XFP-RF QAM Transmitter APC ITU 43 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU45= | XFP-RF QAM Transmitter APC ITU 45 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU46= | XFP-RF QAM Transmitter APC ITU 46 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU47= | XFP-RF QAM Transmitter APC ITU 47 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU49= | XFP-RF QAM Transmitter APC ITU 49 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU50= | XFP-RF QAM Transmitter APC ITU 50 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU51= | XFP-RF QAM Transmitter APC ITU 51 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU53= | XFP-RF QAM Transmitter APC ITU 53 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU55= | XFP-RF QAM Transmitter APC ITU 55 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU56= | XFP-RF QAM Transmitter APC ITU 56 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU58= | XFP-RF QAM Transmitter APC ITU 58 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-ITU59= | XFP-RF QAM Transmitter APC ITU 59 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-iWDM-ITU21= | XFP-RF QAM Transmitter APC iWDM ITU 21 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-iWDM-ITU22= | XFP-RF QAM Transmitter APC iWDM ITU 22 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |

| End-of-Sale Product Part Number | Product Description | Replacement Product Part Number | Replacement Product Description | Additional Information |
|---------------------------------|--|---|---------------------------------|------------------------|
| XFP-RF-IWDM-ITU24= | XFP-RF QAM Transmitter APC iWDM ITU 24 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU26= | XFP-RF QAM Transmitter APC iWDM ITU 26 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU28= | XFP-RF QAM Transmitter APC iWDM ITU 28 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU33= | XFP-RF QAM Transmitter APC iWDM ITU 33 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU36= | XFP-RF QAM Transmitter APC iWDM ITU 36 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU39= | XFP-RF QAM Transmitter APC iWDM ITU 39 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU44= | XFP-RF QAM Transmitter APC iWDM ITU 44 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU48= | XFP-RF QAM Transmitter APC iWDM ITU 48 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU52= | XFP-RF QAM Transmitter APC iWDM ITU 52 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU54= | XFP-RF QAM Transmitter APC iWDM ITU 54 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU57= | XFP-RF QAM Transmitter APC iWDM ITU 57 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU60= | XFP-RF QAM Transmitter APC iWDM ITU 60 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU61= | XFP-RF QAM Transmitter APC iWDM ITU 61 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-IWDM-ITU62= | XFP-RF QAM Transmitter APC iWDM ITU 62 | See the Product Migration Options section below for detailed information on replacing this product. | - | - |
| XFP-RF-T= | XFP-RF QAM Transmitter APC Tunable ITU 20 - ITU 62 | There is currently no replacement product available for this product. | - | - |

Product Migration Options

Customers are encouraged to migrate to the Cisco Prisma II SuperQAM 1.2 Transmitters. Information about this product can be found at:

<http://www.cisco.com/c/en/us/products/collateral/video/prisma-ii/datasheet-c78-734755.html>.

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at:

http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco XFP QAM Transmitters through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <http://www.cisco.com/go/eos>.

Service prices for Cisco products are subject to change after the product End-of-Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to:

http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more Information about the Cisco Prisma II SuperQAM 1.2 Transmitters, visit <http://www.cisco.com/c/en/us/products/collateral/video/prisma-ii/datasheet-c78-734755.html>, or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/products_end-of-life_policy.html.

**For more information about the Cisco Product Warranties, go to:

http://www.cisco.com/en/US/products/prod_warranties_listing.html.

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cisco/support/notifications.html>.

Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:

http://www.cisco.com/web/feeds/products/end_of_life_rss.xml.

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)