

End-of-Sale and End-of-Life Announcement for the Cisco Selected Port Adapters ONLY on the Cisco uBR7246VXR

2313 - Amended

Cisco® announces the end-of-sale and end-of-life dates for the Selected Port Adapters ONLY on the Cisco uBR7246VXR. The last day to order the Selected Port Adapters ONLY on the Cisco uBR7246VXR is April 30, 2004. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for Selected Port Adapters ONLY on the Cisco uBR7246VXR. Table 2 lists the product part numbers affected by this announcement.

This End-of-Sale announcement applies only to the uBR7200 platform. The mentioned port adapters are still supported and available on the Cisco 7200, Cisco 7301, Cisco 7304, Cisco 7500, and Cisco 7600 platforms.

Table 1. End-of-Life Milestones and Dates for the Selected Port Adapters ONLY on the Cisco uBR7246VXR

| Milestone | Definition | Date |
|--|---|---|
| End-of-Life Announcement Date | The date the document that announces the end of sale and end of life of a product is distributed to the general public. | October 14, 2003 |
| End-of-Sale Date | The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date. | April 30, 2004 |
| Last Ship Date: HW | The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time. | August 1, 2004 |
| End of Routine Failure Analysis Date: HW | The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect. | Support will be provided until further notice |
| End of New Service Attachment Date: HW | For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract. | |
| End of Service Contract Renewal Date: HW | The last date to extend or renew a service contract for the product. | |
| Last Date of Support: HW | The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete. | |

This announcement applies only to the uBR7200 platform. The mentioned port adapters are still supported and available on the Cisco 7200, Cisco 7301, Cisco 7304, Cisco 7500, and Cisco 7600 platforms

Table 2. Product Part Numbers Affected only by the uBR7200

| End-of-Sale Product Part Number | Product Description |
|---------------------------------|----------------------------------|
| PA-2H | 2-Port HSSI Port Adapter |
| PA-8T-V35 | 8-Port Serial, V.35 Port Adapter |

Product Migration Options

This announcement applies only to the uBR7200 platform. These port adapters are still supported and available for the Cisco 7200, Cisco 7301, Cisco 7304, Cisco 7500, and Cisco 7600 platforms.

For the above port adapters on the Cisco uBR7246VXR, there is no direct migration to another port adapter using the same technology. Customers can either install a port adapter using the same technology on another Cisco router connected to the Cisco uBR7246VXR or install a port adapter based on a different technology for the Cisco uBR7246VXR.

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Certified Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

<http://www.cisco.com/web/ordering/ciscocapital/refurbished/index.html>

For More Information

For more information about the Cisco End-of-Life Policy, go to:

http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to:

<http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Europe Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: +31 0 800 020 0791
Fax: +31 0 20 357 1100

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

©2006 Cisco Systems, Inc. All rights reserved. CCVP, the Cisco logo, and the Cisco Square Bridge logo are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networking Academy, Network Registrar, Packet, PIX, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0609R)