ılıılı cısco

Product End-of-Life Notice Cisco public

End-of-Sale and End-of-Life Announcement for the Cisco AireOS 3504 Wireless Controller

Contents

Overview	3
End-of-life milestones	3
Product Part Numbers	4
Product Migration Options	5
For More Information	5

Overview

EOL13833

Cisco announces the end-of-sale and end-of life dates for the Cisco AireOS 3504 Wireless Controller. The last day to order the affected product(s) is March 31, 2021 . Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 of the EoL bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement. For customers with active and paid service and support contracts, support will be available under the terms and conditions of customers' service contract.

End-of-life milestones

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	March 31, 2021
End-of-Sale Date : HW,App SW	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 31, 2021
Last Ship Date : HW,App SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 2, 2021
End of SW Maintenance Releases Date : HW,App SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	January 31, 2023
End of Vulnerability/Security Support : HW	The last date that Cisco Engineering may release a planned maintenance release or scheduled software remedy for a security vulnerability issue.	January 30, 2025
End of Routine Failure Analysis Date : HW	The last-possible date a routine failure analysis may be performed to determine the cause of hardware product failure or defect.	January 31, 2022
End of New Service Attachment Date : HW,App SW	For equipment and software that is not covered by a service-and- support contract, this is the last date to order a new service-and- support contract or add the equipment and/or software to an existing service-and-support contract.	January 31, 2022
End of Service Contract Renewal Date : App SW	The last date to extend or renew a service contract for the product.	May 2, 2024
End of Service Contract Renewal Date : HW	The last date to extend or renew a service contract for the product.	May 1, 2026

 Table 1.
 End-of-Life Milestones and Dates for the Cisco AireOS 3504 Wireless Controller

Milestone	Definition	Date
Last Date of Support : App SW	The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.	January 31, 2025
ast Date of Support :The last date to receive applicable service and support for the product as entitled by active service contracts or by warranty terms and conditions. After this date, all support services for the product are unavailable, and the product becomes obsolete.		January 31, 2027

HW = Hardware

OS SW = Operating System Software

App. SW = Application Software

Product Part Numbers

Table 2. Product Part Number	s Affected by This Announcement
------------------------------	---------------------------------

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description	Additional Information
AIR-CT3504- RMNT=	3504 Wireless Controller Rack Mount Tray	There is currently no replacement product available for this product.	-	-
AIR-CT3504-CA- K9	Cisco 3504 Wireless Controller for Service Depot	See Product Migration Options section for details.	Catalyst 9800-L Wireless Controllers	
CT3504 LIC	CT3504 LIC	There is currently no replacement product available for this product.	-	-
AIR-CT3504-CA- K9++	Cisco 3504 Wireless Controller for Service Depot TAA	See Product Migration Options section for details.	Catalyst 9800-L Wireless Controllers	-
AIR-CT3504-K9++	Cisco 3504 Wireless Controller (TAA)	See Product Migration Options section for details.	Catalyst 9800-L Wireless Controllers	-
EDU-LIC-CT3504- UPG	K12 SKU for 3504 AP Adder Licenses	There is currently no replacement product available for this product.	-	-
LIC-CT3504-1AP- INT	Cisco 3504 Wireless Controller 1 AP Lic integrated with AP	There is currently no replacement product available for this product.	_	-
LIC-CT3504-INT- 1A	1 AP license to attach with AP bundle (cannot be ordered)	There is currently no replacement product available for this product.	-	-

Product Migration Options

Customers may be able to use the Cisco Technology Migration Program (TMP) where applicable to trade-in eligible products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, customers should work with their Cisco Partner or Cisco account team. Cisco Partners can find additional TMP information on Partner Central at http://www.cisco.com/web/partners/incentives_and_promotions/tmp.html.

Customers may be able to continue to purchase the Cisco AireOS 3504 Wireless Controller through the Cisco Certified Refurbished Equipment program. Refurbished units may be available in limited supply for sale in certain countries on a first-come, first-served basis until the Last Date of Support has been reached. For information about the Cisco Certified Refurbished Equipment program, go to: <u>http://www.cisco.com/go/eos</u>.

Service prices for Cisco products are subject to change after the product End of Sale date.

The Cisco Takeback and Recycle program helps businesses properly dispose of surplus products that have reached their end of useful life. The program is open to all business users of Cisco equipment and its associated brands and subsidiaries. For more information, go to: http://www.cisco.com/web/about/ac227/ac228/ac231/about_cisco_takeback_recycling.html.

For More Information

For more information about the Cisco End-of-Life Policy, go to: <u>http://www.cisco.com/en/US/products/products_end-of-life_policy.html</u>

For more information about the Cisco Product Warranties, go to: http://www.cisco.com/en/US/products/prod warranties listing.html

To subscribe to receive end-of-life/end-of-sale information, go to: http://www.cisco.com/cisco/support/notifications.html

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.

Americas Headquarters Cisco Systems, Inc. San Jose, CA Asia Pacific Headquarters Cisco Systems (USA) Pte. Ltd. Singapore Europe Headquarters Cisco Systems International BV Amsterdam, The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at https://www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: https://www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA