



End-of-Life Announcement for Cisco Aironet Wireless LAN Antenna Cables

Product Bulletin No. 1622

As part of our continuing effort to enhance the Cisco Aironet® product line, Cisco Systems is pleased to announce new, improved wireless LAN antenna cables and the End-of-Life of Cisco Aironet antenna cables as per the descriptions and schedules detailed below. The new cables are the suggested replacements for the discontinued cables.

EoL Part Numbers	Description	Last Order Date	Last Support Date	Suggested Replacements (New Cables)	Description of Suggested Replacements
AIR-420-003346-020	20 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB020LL-R	20-ft. low-loss cable with RP-TNC connectors
AIR-420-003346-050	50 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB050LL-R	50-ft. low-loss cable with RP-TNC connectors
AIR-420-003346-075	75 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB100ULL-R	100-ft. ultra-low-loss cable with RP-TNC connectors
AIR-420-003346-100	100 ft. cable with RP-TNC connectors	February 27, 2002	February 27, 2007	AIR-CAB100ULL-R or AIR-CAB150ULL-R	100-ft. ultra-low-loss cable with RP-TNC connectors or 150-ft. ultra-low-loss cable with RP-TNC connectors

The new outdoor-rated, low-loss cables have improved insulation and are far less susceptible to water penetration than the previous cables. In addition, the new 100- and 150-foot ultra-low-loss cables now feature 4.4 dB loss per 100 feet, greatly improving the quality of the radio signal and range when applications require expanded cable lengths.




Americas Headquarters
Cisco Systems, Inc.
San Jose, CA

Asia Pacific Headquarters
Cisco Systems (USA) Pte. Ltd.
Singapore

Europe Headquarters
Cisco Systems International BV Amsterdam,
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at www.cisco.com/go/offices.

 Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Printed in USA