



# End-of-Sale and End-of-Life Announcement for the 3eTI Driver for Cisco Secure Services Client (SSC) FIPS

## EOL7943—Amended

Cisco announces the end-of-sale and end-of life dates for the 3eTI Driver for Cisco Secure Services Client (SSC) FIPS. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product(s). Table 2 lists the product part numbers affected by this announcement.

**Table 1.** End-of-Life Milestones and Dates for the 3eTI Driver for Cisco Secure Services Client (SSC) FIPS

Milestone	Definition	Date
<b>End-of-Life Announcement Date</b>	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	December 26, 2011
<b>End-of-Sale Date</b>	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	December 26, 2011

HW = Hardware OS SW = Operating System Software App. SW = Application Software

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description
<b>AIR-SSCFIPS-DRV</b>	3eti driver for Cisco Secure Services Client (SSC) FIPS
<b>AIR-SSCFIPS-DRV-L1</b>	Specified seat count up to 250
<b>AIR-SSCFIPS-DRV-L2</b>	Specified seat count in range 251-1000
<b>AIR-SSCFIPS-DRV-L3</b>	Specified seat count in range 1001-2500
<b>AIR-SSCFIPS-DRV-L4</b>	Specified seat count in range 2501-5000
<b>AIR-SSCFIPS-DRV-L5</b>	Specified seat count in range 5001-10000
<b>AIR-SSCFIPS-DRV-L6</b>	Specified seat count in range 10001-25000
<b>AIR-SSCFIPS-DRV-L7</b>	Specified seat count in range 25001-50000
<b>AIR-SSCFIPS-DRV-L8</b>	Specified seat count in range 50001-100000

## Product Migration Options

There is no replacement available for the 3eTI Driver for Cisco Secure Services Client (SSC) FIPS at this time.

There is no migration path for this product.

## For More Information

For more information about the Cisco End-of-Life Policy, go to:

[http://www.cisco.com/en/US/products/products\\_end-of-life\\_policy.html](http://www.cisco.com/en/US/products/products_end-of-life_policy.html)

---

For more information about the Cisco Product Warranties, go to:  
[http://www.cisco.com/en/US/products/prod\\_warranties\\_listing.html](http://www.cisco.com/en/US/products/prod_warranties_listing.html)

To subscribe to receive end-of-life/end-of-sale information, go to:  
<http://www.cisco.com/cisco/support/notifications.html>

### Subscribe for RSS Notifications for End-of-Life and End-of-Sale Notices

To subscribe to the End-of-Life and End-of-Sale RSS Feed, insert the following URL into your RSS application:  
[http://www.cisco.com/web/feeds/products/end\\_of\\_life\\_rss.xml](http://www.cisco.com/web/feeds/products/end_of_life_rss.xml)

Any authorized translation issued by Cisco Systems or affiliates of this end-of-life Product Bulletin is intended to help customers understand the content described in the English version. This translation is the result of a commercially reasonable effort; however, if there are discrepancies between the English version and the translated document, please refer to the English version, which is considered authoritative.



---

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)