



## Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats:

- The *Open Caveats* sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



**Note** The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search, on page 1](#)
- [Open Caveats in Cisco Smart PHY 1.1.14, on page 1](#)

## Cisco Bug Search

Cisco Bug Search Tool (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>.

## Open Caveats in Cisco Smart PHY 1.1.14

Caveat ID Number	Description
<a href="#">CSCvh16807</a>	Configuration: Out of band config resources re-allocated
<a href="#">CSCvh48512</a>	Admin Credentials and SNMP Community Strings cannot be modified once set
<a href="#">CSCvh52216</a>	Clearing RPD Pairing while Standby LC is Active can cause inconsistencies
<a href="#">CSCvh74133</a>	RPD Product Type on the UI is RPD-1-CHASS for all RPDs (vRPD, 6x12, shelf)
<a href="#">CSCvh81376</a>	If RPD Add-to-DLM fails, the subsequent Update-to-DLM will fail

<b>Caveat ID Number</b>	<b>Description</b>
<a href="#">CSCvh85671</a>	NC Video SG / RPD Name / RPD Description not imported from CSV file v1.1.13
<a href="#">CSCvh87330</a>	NSO sync is taking around 20 to 25 minutes when cBR8 chassis is fully loaded
<a href="#">CSCvh94364</a>	Under Global Config, Router Vendor field should be changed to Router Product Type
<a href="#">CSCvh80626</a>	DS Sharing: CLI Channel Config pushed is incorrect for RPD and rejected
<a href="#">CSCvh95939</a>	Cable: Auto-logout even when using the application