



Cisco uBR7100 Universal Broadband Router Documentation Roadmap

Documentation Survey

Is Cisco documentation helpful? Click [here](#) or go to <http://www.cisco.com/go/techdocideas> to give us your feedback.

Contents

Use this roadmap as an online directory to quickly access publications for your product. It corresponds to the [Cisco uBR7100 documentation index page](#), and includes the following sections:

- [General Information, page 1](#)
- [Downloads, page 2](#)
- [Reference Guides, page 2](#)
- [Design, page 2](#)
- [Install and Upgrade, page 4](#)
- [Configure, page 4](#)
- [Troubleshoot and Alerts, page 5](#)

General Information

To open a document, click the link provided.

Compatibility Information

- [Software Advisor - Choose The Software For Your Network Device](#)



Corporate Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Copyright © 2005–2006 Cisco Systems, Inc. All rights reserved.

Documentation Roadmaps

- [Cisco uBR7100 Universal Broadband Router Documentation Roadmap](#)

Release Notes

- [Cisco uBR7100 Series Release Notes](#)
- [Release Notes for Cisco uBR7100 Series for Cisco IOS Release 12.1 EC](#)

Downloads

To display the Downloads page, click [here](#) or go to <http://www.cisco.com/cisco/web/download/index.html>.



Note

You must have a Cisco.com account to access the Downloads page. To register with Cisco.com, click [here](#) or go to <http://tools.cisco.com/RPF/register/register.do>.

From the Downloads page, you can access:

- Software Products & Downloads—Cisco IOS Software, Access Software, Cable/Broadband Software, Cisco Secure Software, LAN Switching Software, Network Management Software, Optical Software, Reseller Software, Storage Networking Software, Voice Software, Web Software, Wireless Software.
- Software Utilities—Software License Registration, Software Registration, Special File Access, Aironet Wireless Software Selector.
- General Information—Product Information, Using the Software Center.

Reference Guides

To open a document, click the link provided.

Command References

- [Cisco Broadband Cable Command Reference Guide](#)
- [Command Lookup Tool for Cisco IOS](#)

Design

To open a document, click the link provided.

Design TechNotes

- Using the max-cpe Command in the DOCSIS and CMTS

Install and Upgrade

To open a document, click the link provided.

Install and Upgrade Guides

- [Regulatory Compliance and Safety Information for the Cisco uBR7100 and Cisco uBR7100E Series Universal Broadband Routers](#)
- [Cisco uBR7100 Series Hardware Installation Guide](#)
- [Hardware Installation Guide : Cisco uBR7100 series \(PDF\)](#)

Install and Upgrade TechNotes

- [Software Installation and Upgrade Procedures](#)

Configure

To open a document, click the link provided.

Configuration Examples and TechNotes

- [Configuring cable modem remote-query Command](#)
- [Configuring the UBR 7100 in Bridge Mode](#)

Configuration Guides

- [Cisco Feature Navigator II](#)
- [Cisco uBR7100 Series Software Configuration Guide](#)

Feature Guides

- [Cisco CMTS Feature Guide](#)
- [Configuring Telco Return](#)

Troubleshoot and Alerts

To open a document, click the link provided.

Error and System Messages

- [Cisco CMTS Error Messages](#)
- [Error Message Decoder](#)

Field Notices

- [Cisco uBR7114 Universal Broadband Router—Field Notice: FN - 61986 - uBR7100 Series may Exhibit SNR Issues Over Time - Hardware Upgrade may be Needed](#)
- [Cisco uBR7114E Universal Broadband Router—Field Notice: FN - 61986 - uBR7100 Series may Exhibit SNR Issues Over Time - Hardware Upgrade may be Needed](#)
- [Cisco uBR7111 Universal Broadband Router—Field Notice: FN - 61986 - uBR7100 Series may Exhibit SNR Issues Over Time - Hardware Upgrade may be Needed](#)
- [Cisco uBR7111E Universal Broadband Router—Field Notice: FN - 61986 - uBR7100 Series may Exhibit SNR Issues Over Time - Hardware Upgrade may be Needed](#)
- [Field Notice: Year 2000 Product Compliance Table Update](#)
- [Field Notice: Some 7200 I/O Controllers May Not Boot with NPE-100, NPE-150, and NPE-200 Cards](#)
- [Field Notice: Adding a 25th Netmask to a Network Database May Cause a Software Forced Crash](#)
- [Field Notice: Router May Fail To Boot when Bootflash Contains Non-Bootable Code](#)
- [Field Notice: RM7000 Processors Execute Instructions Incorrectly](#)
- [Field Notice: Mandatory IOS Upgrade for Cisco 7200 and CVPN 7100 Series Routers Running SA-ISA or SM-ISM HW Encryption Cards](#)
- [Field Notice: Minimum Recommended Cisco IOS Software for Cisco 7120/40 VPN Routers with QED 2.1](#)
- [Field Notice: New Boot ROM For Cisco 71xx Platforms Improves Flash Disk Boot Up Reliability](#)
- [Field Notice: Year 2000 Product Compliance Table Update](#)

Password Recovery

- [Password Recovery Procedure for the Cisco uBR7100, uBR7200, uBR10000 Universal Broadband Router](#)

Security Advisories and Notices

- [Cisco Security Advisory: Cable Modem Termination System Authentication Bypass](#)

Troubleshooting Guides

- [Bug Toolkit](#)
- [Output Interpreter](#)

Troubleshooting TechNotes

- [Bug Toolkit](#)
- [Output Interpreter](#)
- [Cable Modems Dropping Offline in a 2-way Cable Network](#)
- [DOCSIS 1.0 Baseline Privacy on the Cisco CMTS](#)
- [ROMmon Recovery Procedure for the Cisco 7200, 7300, 7400, 7500, RSP7000, Catalyst 5500 RSM, uBR7100, uBR7200, uBR10000, and 12000 Series Routers](#)
- [Software Installation and Upgrade Procedures](#)
- [Using the max-cpe Command in the DOCSIS and CMTS](#)

Copyright © 2005-2006 Cisco Systems, Inc. All rights reserved. Cisco, Cisco IOS, Cisco Systems, and the Cisco Systems logo are registered trademarks of Cisco Systems, Inc. or its affiliates in the U.S. and certain other countries. All other brands, names, or trademarks mentioned in this document or Web site are the property.

♻️ Printed in the USA on recycled paper containing 10% postconsumer waste.