



## Caveat List

This chapter describes open severity 1 and 2 caveats and select severity 3 caveats.

The *Open Caveats* section lists open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.

The bug IDs are sorted alphanumerically.



**Note** The *Caveats* section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Cisco Bug Search, on page 1](#)
- [Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.1, on page 2](#)
- [Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.1, on page 2](#)

## Cisco Bug Search

Use the [Cisco Bug Search Tool](#) to access open and resolved bugs for a release.

The tool allows you to search for a specific bug ID, or for all bugs specific to a product and a release.

Save Search Load Saved Search Clear Search Email Current Search

Search For:

Examples: CSCid10124, router crash, etc...

Product: Series/Model

Releases: Affecting or Fixed in these Release:

If you have a specific bug ID, enter it here

Start typing product name to view suggestions or expand list to choose your product

Select from list

Enter release number

366025

You can filter the search results by last modified date, bug status (open, resolved), severity, rating, and support cases.

Save Search Load Saved Search Clear Search Email Current Search

Search For:  Examples: CSCid10124, router crash, etc...

Product:  Series/Model  Select from list

Releases:  Affecting or Fixed in these Release:

Filter:  Modified Date:  Status:  Severity:  Rating:  Support Cases:  Bug Type:  Customer Visible

Viewing 1 - 25 of 132 results Sort by  Export Results to Excel

3668026

## Open Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.1

Caveat ID Number	Description
<a href="#">CSCvh83290</a>	RPHY: interop: PtpRpdEnetPortIndex(TLV 86.4) has always been set to 1.
<a href="#">CSCvk32107</a>	Sensor "PS1_N6V_MON" (id 44) not available on RPD node with GS7000 (rpd side).
<a href="#">CSCvk38899</a>	PTP state shown as PHASE_LOCK wrongly for a unreachable PTP primary.

## Resolved Caveats for Cisco 1x2 / Compact Shelf RPD Software 5.1

Caveat ID Number	Description
<a href="#">CSCvh69421</a>	PTP status will become hold-over soon after RPD online with dual PTP primary