



## New and Changed Information

---

- [New and Changed Information](#), on page 1

## New and Changed Information

*Table 1: New and Changed Features*

Feature	Description	Changed in Release	Where Documented
Support for HA on N9K-C9804	Dual-Supervisors support for High Availability is provided on Cisco Nexus 9804 switches.	10.4(2)F	<a href="#">System-Level High Availability</a>
Support for HA on N9K-C9808	Dual-Supervisors support for High Availability is provided on Cisco Nexus 9808 switches.	10.4(1)F	<a href="#">System-Level High Availability</a>

