

New and Changed Information

This chapter contains the following sections:

• New and Changed Information, on page 1

New and Changed Information

The following tables provide an overview of the significant changes to this guide up to this current release. The table does not provide an exhaustive list of all changes made to the guide or of the new features up to this release.

Feature	Description	Where Documented
Link Flap Policies	A link flap policy specifies when to disable a switch port due to link flapping errors.	Link Flap Policies
Port Bring-up Delay	When you configure a link level policy, you can set the Port bring-up delay (milliseconds) parameter, which specifies a time in milliseconds that the decision feedback equalizer (DFE) tuning is delayed when a port is coming up. The delay is used to help avoid CRC errors during link bringup when using some third-party adapters.	Port Bring-up Delay
First Time Setup of SNMP and Syslog	The First Time Setup wizard now includes initial configuration of Syslog monitoring destinations and of SNMP external management and trap destinations.	First Time Setup Wizard

Table 1: New Features and Changed Information for Cisco APIC Release 5.0(1)

I