



## New and Changed Information

---

This chapter contains the following sections:

- [Change Summary, on page 1](#)

### Change Summary

*Table 1: New and Changed Features*

Feature	New or Changed Topics	Changed in Release	Where Documented
ISL Diagnostics	This feature introduces commands to test the health of interswitch links.	7.3(0)D1(1)	<a href="#">Configuring Interswitch Link Diagnostics</a>
Configuring Scripts for Call Home Alerts	This feature allows you to map a script to the Call Home alert type that should trigger the alert.	7.3(1)DY(1)	<a href="#">Configuring Call Home</a>

