

Caveats

- Cisco Bug Search Tool, on page 1
- Open Caveats in Cisco IOS XE Dublin 17.10.x, on page 1
- Resolved Caveats in Cisco IOS XE Dublin 17.10.1, on page 1

Cisco Bug Search Tool

The Cisco Bug Search Tool (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click on the identifier.

Open Caveats in Cisco IOS XE Dublin 17.10.x

Identifier	Headline
CSCwb73326	Beacon LED glows on a new switch just after bootup
CSCwd17787	Dynamic private vlan by dot1x stopped working after upgrading to 16.12.x and above
CSCwd56540	Ignore higher fan speed deviations on 9200

Resolved Caveats in Cisco IOS XE Dublin 17.10.1

There are no resolved caveats in this release.

Resolved Caveats in Cisco IOS XE Dublin 17.10.1