



New and Changed Information for this Release

This chapter contains the following section:

- [New and Changed Information for this Release, on page 1](#)

New and Changed Information for this Release

The following table provides an overview of the significant changes to this guide for this current release. The table does not provide an exhaustive list of all changes made to this guide or of all new features in this release.

Table 1: New Features and Changed Behavior in Cisco IMC Supervisor, Release 2.3(4.0)

Feature	Description	Where Documented
Support for launching KVM console for a Rack-Mount Server	<p>You can continue to launch the KVM console for C-Series M4 or C-Series M5 servers running on firmware version 4.1(1c) or later.</p> <p>Note The launch of KVM console for servers running firmware versions below 4.1(1c) is deprecated and will not work as expected.</p>	Launching KVM Console for a Rack-Mount Server

