

Dear Cisco Customer,

Cisco engineering has identified the following software issues with the release that you have selected that may affect your use of this software. Please review the Software Advisory notice here to determine if the issues apply to your environment. You may proceed to download this software if you have no concerns with the issue described.

For more comprehensive information about what is included in this software, refer to the Cisco software Release Notes, available from the [Product Selector tool](#). From this page, select the product you are interested in. Release Notes are under "General Information" on the product page.

Affected Software and Replacement Solution for CSCuw44524		
Software Type	Software Affected	Software Solution
UCS C-Series Standalone Server SW	Version: 2.0(6d), 2.0(8d) Affected Images: ucs-c460m4-huu-2.0.6d.iso ucs-c460m4-huu-2.0.8d.iso	Version: 2.0.(8g) Replacement Images: ucs-c460m4-huu-2.0.8g.iso
UCS Server B and C bundles	Version: 2.2(5a), 2.2(5b), 2.2(5c), 2.2(6c), 2.2(6d) B and C Bundles Affected Images: ucs-k9-bundle-c-series.2.2.5a.C.bin ucs-k9-bundle-c-series.2.2.5b.C.bin ucs-k9-bundle-c-series.2.2.5c.C.bin ucs-k9-bundle-c-series.2.2.6c.C.bin ucs-k9-bundle-c-series.2.2.6d.C.bin ucs-k9-bundle-b-series.2.2.5a.B.bin ucs-k9-bundle-b-series.2.2.5b.B.bin ucs-k9-bundle-b-series.2.2.5c.B.bin ucs-k9-bundle-b-series.2.2.6c.B.bin ucs-k9-bundle-b-series.2.2.6d.B.bin	Version: 2.2(6e) Replacement Images: ucs-k9-bundle-c-series.2.2.6e.C.bin ucs-k9-bundle-b-series.2.2.6e.B.bin

Reason for Advisory:

This software advisory addresses one software issues.

CSCuw44524

C460 M4, B260 M4, B460 M4 with E7 v2 clear CMOS can cause UECC Error

Affected Platforms:

C460 M4, B260 M4, B460 M4

<i>Platform</i>	<i>PID</i>
<i>C460 M4</i>	<i>UCSC-C460-M4/UCSC-C460-M4=/UCSC-C460-M4-CH</i>
<i>B260 M4</i>	<i>UCSB-EX-M4-1C-U/ UCSB-EX-M4-1=/UCSB-EX-M4-1C-CH</i>
<i>B460 M4</i>	<i>UCSB-EX-M4-1A-U/ UCSB-EX-M4-1=/ UCSB-EX-M4-1A-CH</i>

For UCS C460 M4, B260 M4, C460 M4 systems with E7 v2, please refer to [CSCuw44524](#) prior to download.