



New and Changed Information

- [New and Changed Information](#), on page 1

New and Changed Information

This section provides information on new feature and changed behavior in 4.3(2b), Release 4.3.

Table 1: New Features and Changed Behavior in 4.3(2c), Release

| Feature | Description | Where Documented |
|--|--|------------------|
| Support for Cisco UCS X-Series servers | Cisco UCS Manager supports Cisco UCS X410c M7 Compute Node. Cisco UCS X-Series servers support Intelligent Fabric Modules (IFM), which function similarly to the Input/Output Module (IOM) in Cisco UCS B-Series servers. | — |
| Support for Cisco UCS VIC cards | Cisco UCS Manager supports the following Cisco UCS VIC cards: <ul style="list-style-type: none"> • Cisco UCS VIC 15230 • Cisco UCS VIC 15237 MLOM • Cisco UCS VIC 15427 | — |

Table 2: New Features and Changed Behavior in 4.3(2b), Release

| Feature | Description | Where Documented |
|--|--|--|
| Support for Power Capping and Power Management for Cisco UCSX-9508 Chassis | Cisco UCS Manager now supports Power Capping and Power Management for Cisco UCSX-9508 Chassis. | Power Capping in Cisco UCS |

| Feature | Description | Where Documented |
|--|--|--|
| Support for Cisco UCS X9508 server chassis with Cisco UCS X-Series servers | <p>Cisco UCS Manager supports Cisco UCSX-9508 Chassis with the following Cisco UCS X-Series servers:</p> <ul style="list-style-type: none"> • Cisco UCS X210c M7 Compute Node • Cisco UCS X210c M6 Compute Node <p>Cisco UCS X-Series servers support Intelligent Fabric Modules (IFM), which function similarly to the Input/Output Module (IOM) in Cisco UCS B-Series servers.</p> | — |
| Support Cisco UCS C-Series M7 servers | <p>Cisco UCS Manager now supports the following C-Series M7 servers:</p> <ul style="list-style-type: none"> • Cisco UCS C240 M7 Server • Cisco UCS C220 M7 Server | Power Capping in Cisco UCS |
| Support for Cisco UCS X9508 Server Chassis equipped with X-Fabric Module (XFM) | Cisco UCS Manager introduces inventory support for Cisco UCS X9508 Server Chassis equipped with X-Fabric Module (XFM) | Viewing X-Fabric Module (XFM) Fan Status |
| Support for Cisco UCS 6200 Series Fabric Interconnect is deprecated | Cisco UCS Manager deprecates support for Cisco UCS 6200 Series Fabric Interconnects. | — |
| Support for Cisco UCS M4 servers are deprecated | Cisco UCS Manager deprecates support for UCS B-series, C-series, and S-series M4 servers. | — |