

# Release Notes for Cisco D9865 Satellite Receiver Version 2.80

**First Published: 2017-12-07** 

## **Overview**

This document describes the new features, resolved caveats, and open caveats in Version 2.80 for the Cisco D9865 Satellite Receiver.

#### **New Features**

The following is a list of new features for Version 2.80:

• Allows Closed Captions output on VBI line 18 when the D9865 is configured to convert NTSC frame rate input video containing Closed Captions data to PAL-N video format. The Normal Line 21 Closed Captions output for NTSC video formats, with input NTSC video, is not affected.



Note

Closed Captions is available only in the CVBS video output regardless of video format.

 Reduced the duration of the Video Format Mismatch blue alert screen that appears in the video output when the D9865 first detects that incoming video frame rate and outgoing video frame rate are configured differently.

## **Caveats**

This section includes open and resolved caveats for this release. This section includes the following topics.

- Open Caveats Version 2.80, on page 1
- Resolved Caveats Version 2.80, on page 2

### **Open Caveats - Version 2.80**

There are no open caveats for Version 2.80.

#### **Resolved Caveats - Version 2.80**

The following lists a resolved caveat in Version 2.80. The caveat ID can be searched using the Cisco Bug Search Tool (https://tools.cisco.com/bugsearch), where you can find details about the caveat.

Bug ID	Description
CSCvd41063	In non-standards compliant streams, PAT does not identify the NIT PID.
CSCvf78721	Small MPE frames are dropped.

# **Obtaining Documentation and Submitting a Service Request**

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see What's New in Cisco Product Documentation.

To receive new and revised Cisco technical content directly to your desktop, you can subscribe to the What's New in Cisco Product Documentation RSS feed. RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <a href="http://www.cisco.com/go/trademarks">http://www.cisco.com/go/trademarks</a>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

 $^{\tiny{\textcircled{\scriptsize 0}}}$  2017 Cisco Systems, Inc. All rights reserved.