



New and Changed Information

- [New and Changed for Firmware Release 11.2\(4\), on page 1](#)
- [New and Changed for Firmware Release 11.2\(3\), on page 1](#)
- [New and Changed for Firmware Release 11.2\(2\), on page 2](#)
- [New and Changed for Firmware Release 11.2\(1\), on page 2](#)

New and Changed for Firmware Release 11.2(4)

Revision	New and Changed
Updated the <code>FAX Enable T38</code> parameter for the feature <i>Outbound Fax Refinement</i>	Audio Configuration
Updated the topics for the feature <i>OPTIONS Support in NAT Keep Alive Messages</i>	NAT Settings
Added the missing topic for the feature <i>Log Management for Users</i>	Crash Dump
Updated the topics for the feature <i>Default Web Access Protocol Changes to HTTPS</i>	Access the Phone Web Interface Cisco ATA 192 Web Access Fields Cisco ATA 191 Web Access Fields Cisco ATA 192 Remote Access Fields Troubleshoot Your Fax
Updated the topics for the feature <i>Increased Maximum Number of A Records for SRV Record</i>	SIP Proxy Redundancy

New and Changed for Firmware Release 11.2(3)

Revision	New and Changed
Added the topic for the <code>HTTP Proxy Support</code> feature	HTTP Proxy (ATA 191 and 192)

Revision	New and Changed
Updated the topics to add the value range of the parameters <code>Call Back Delay</code> , <code>VMWI Refresh Intvl</code> , <code>DTMF Playback Length</code> , <code>DTMF Playback Level</code> , and <code>DTMF Twist</code>	Control Timer Values (Sec) Miscellaneous

New and Changed for Firmware Release 11.2(2)

Revision	New and Changed
Updated the parameter <code>SIP Transport</code>	SIP Settings
Updated the topic to add the new feature <code>DNS NAPTR Support</code>	Other ATA Voice Quality Features
Updated the topic to add more examples	SIP Proxy Redundancy
Added the topic for the SIP proxy redundancy feature	SIP Proxy Failover SIP Proxy Fallback
Updated the topic to add the parameter <code>Auto Register When Failover</code>	Proxy and Registration
Updated the topic to mention the maximum number of NAPTR records and SRV records supported in a query	SIP Proxy Redundancy
Added a new task topic on how to secure a line by automatic SRTP/RTP selection	Set up a Secure Line
Updated the Call Feature Settings table with a new parameter <code>Secure Call Option</code>	Call Feature Settings

New and Changed for Firmware Release 11.2(1)

Revision	New and Changed
Updated the navigation path	Debug Log Module
Added the topics for the E911 feature	Emergency Calls Emergency Call Support Background Emergency Call Support Terminology Configure the ATA to Make Emergency Calls E911 Geolocation Configuration

Revision	New and Changed
Updated RTP Parameters table to add the Call Statistics parameter	RTP Parameters
Added a topic for the reporting End-of-Call Statistics feature	Call Statistics are Not Available in the Server
Added a task for the remote PRT generation feature	Generate a Problem Report Remotely
Updated the topic for the remote PRT generation feature	PRT Viewer
Added a topic how to address the issue when ATA 11.1.0MSR3-9 and older doesn't upgrade	ATA with Firmware Release 11.1.0MSR3-9 and Older Doesn't Upgrade

